### कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल– एम 4 राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार) 9वां तल, एम.एस.ओ. भवन, नई दिल्ली– 110002

दूरभाष: 23319795/ फैक्स: 23317728

<del>По. 23(25) /СЕМ-4/РWD/GNCTD/ 2576</del>



#### O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE –M4 GNCTD, 9<sup>TH</sup> FLOOR, M.S.O. BUILDING I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728 Email:cepwddelhimzm4@gmail.com

दिनॉक: - 12/06/2014

# **Inspection Note**

The Chief Engineer, PWD Maintenance Zone M-4 has inspected roads/works under PWD Division M-313/M-311, along with Sh. N.K Bansal, S.E M-31 & Sh.Bishamber Dass, E.E M-313 on 03-06-2014. Following observations have been made:

### **Delhi University Campus**

The Delhi University Campus roads inspected along with Commissioner, Transport and Dr. Tiwari & ACP, Traffic Police

- Dr. Tiwari insisted to remove the divider provided between NMV lane & main carriageway at Khalsa College. But, it was informed by the field staff that the Delhi University Campus was developed during Common Wealth Games 2010. The NMV lane was planned to accommodate cycles & rickshaws etc. in this area. Thus at this stage it may not be possible to merge the NMV lane with main carriageway.
- DU authorities suggested to lower the floor level of all bus stops at least matching with the adjoining footpath as it is difficult to use by differently abled persons. The Commissioner, Transport informed that the bus shelter floor was raised by PWD. It was pointed out by SE/M-31 that the bus shelters were constructed by DTC as per their standard specifications/drawing, thus the matter of lowering of floor level of bus shelters may be dealt by Commissioner, Transport or the authority who constructed the bus shelters.
- E.E M-313 was instructed to follow drawings prepared by the Consultants. EE may also visit Lodhi road area to see arrangements made for NMV lane at intersections.
- At locations, it is observed that the drain covers were placed unevenly after de-silting. These should be placed in proper level.
- At many places, cracks and local depressions are noticed in the road surface. These should be rectified urgently.
- The central verge near intersection is damaged. The damaged portion of kerb stone should be replaced.
- The small ramps as suggested by Dr.Tiwari should be provided at the bus shelters for proper movement/access of wheel chair.
- At places, continuity of tactile breaks due to erection of electric poles or other reasons. It should be connected making loop at such locations.
- The broken trees, branches, tree leafs etc. still not removed from the footpath of university. The Horticulture wing has to be informed to remove these immediately.
- It was observed that old Electric poles have not been removed after upgradation of street lights. These old non functional poles should be removed on priority.

## Main road passes through Wazirpur Industrial Area

- The progress of work is slow. As already discussed at site one more slip paver should be brought to take up the concreting work from both ends of roads for early completion.
- About 30metre length of drain is still incomplete. The work was in progress and it should be completed in next 10 days.

## Remodelling & desilting of covered S.W. Drain in Jahangirpuri Area

 The work has just started. The opening made in RCC top slab of drain for cleaning of drain should be protected with protection wall around. The work should be completed by end of the month.

> (जयेश कुमार) मुख्य अभियंता अनुरक्षण अंचल– एम 4

## प्रतिलिपि:-

1. सचिव, लो०नि०वि०, ५वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली ११०००२ को सूचनार्थ प्रेषित।

2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

1 श्री एन. के. बंसल, अधीक्षण अभियंता, एम—31, रोहतक रोड क्रासिंग, रिंग रोड, पंजाबी बाग, नई दिल्ली।

2 श्री रमेश कुमार गर्ग, अधीक्षण अभियंता, एम—35, 6वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002 को सूचनार्थ एवं आवश्यक कार्यावाही हेतु प्रेषित।

3 श्री संतोष कुमार, निदेशक (उद्यान), लो०नि०वि०, 13वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002।

4 श्री बिशमबर दास, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 313 लो० नि० वि०, खालसा कालेज के सुप्रमर्ने, माल रोड, दिल्ली—110054।

5 गार्ड फाईल।

मुख्य अभियंता अनुरक्षण अंचल– एम 4