

कार्यालय अधीक्षण अभियन्ता  
लोक निर्माण विभाग,  
सड़क अनुरक्षण परिमंडल-एम 44  
सुखदेव विहार, मथुरा रोड,  
नियर ओखला फ्लाई ओवर,  
नई दिल्ली-110025



O/o THE SUPERINTENDING ENGG.  
ROAD MAINTENANCE CIRCLE-M44,  
PWD (GNCTD), Sukhdev Vihar,  
Mathura Road, Near Okhla Flyover,  
New Delhi-110025  
Phone: 26923611 Fax: 26923613  
E-mail: sepwddelhim44@gmail.com

सं: 23(47)/अधी0अभि0/एम-44/लोनिवि/दि.स-/2014-15/ 81717 दिनांक: 19 .06.2014

**INSPECTION NOTE OF SHRI M.K. MALLICK, SUPERINTENDING ENGINEER, M-44,  
PWD (GNCTD) ON 19.06.2014 OF THE ROADS UNDER THE JURISDICTION OF M-441**

The following roads were inspected on 19.06.2014 in presence of EE/M-441. The following observations were made:

**A) GURU RAVI DASS MARG ( ROAD NO.14 ) :**

- i) Malba seen at places along the footpath, kerb channel & central verge.
- ii) Kerb Stones broken at places and depression in footpath at few places.
- iii) Unauthorized parking seen on carriageway. It is to be immediately removed.
- iv) Unauthorized vendors are running their activities on carriageway.
- v) Malba seen in central verge at places, it is to be cleaned.
- vi) Central verge nosing broken at places, not maintained properly.

**B) OKHLA ESTATE ROAD (ROAD NO.13) :**

- i) Malba and pipes were seen at junction of Road No. 13 and Road No. 14.
- ii) Central verge not properly maintained.
- iii) Unauthorized camp of MCD to be removed.
- iv) Abandoned big stones of MCD to be removed near PWD sub division office.
- v) Newly constructed/repared kerb stones damaged/disturbed at few places.
- vi) At Crown Plaza crossing Road cutting seen, surface of carriageway damaged and cutting in slip road noticed.