

**कार्यालय मुख्य अभियंता**

लोक निर्माण विभाग, अनुसूचना अंचल- एम 4


राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

न०. 23(25)/CEM-4/PWD/GNCTD/ 859



**O/o THE CHIEF ENGINEER**

PWD MAINTENANCE ZONE -M4

GNCTD, 9<sup>TH</sup> FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

दिनांक: - 3 /07/ 2014

**Inspection Note**

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected following roads under M-44, along with Shri M.K. Mallick, Superintending Engineer, M-44, Shri Rakesh Viz, Executive Engineer, M-441 & Shri R. S. Garg, Executive Engineer, M-442 on 28/06/2014. Following observations have been made:-

**A) OUTER RING ROAD :**

- i) Malba was lying in central verge.
- ii) Plants were dry and kerb stones were lying in central verge.
- iii) Kerb stones were lying on footpath near GK-I, T-junction.
- iv) Malba of drain was lying.
- v) Patch repair works to be done near Nehru Place.

**B) S.A.MARG:**

- i) Central verge not clear and plants need to be added.
- ii) Debris/malba was lying near bell mouths.
- iii) Depressed footpath broken and malba was lying.
- iv) Reliance has cut the side road of SA Road and did not restore.
- v) Delhi Jal Board has also cut the road, needs to be filled up. At one place leakage of DJB pipe line seen observed.
- vi) RCC slab of drain broken, area needs to be covered by slab.
- vii) Construction materials were lying at one side on the footpath where building is being constructed.
- viii) Footpath broken and malba lying at a no. of places.

**C) M.G.Road:**

- i) Kerb Channel to be cleaned.
- ii) At Lal Kuan FOB, construction material is yet to be brought to site.
- iii) Malba lying near container depot area.
- iv) Construction material lying on side roads.
- v) NHAI area not properly maintained at Pul Prahladpur.
- vi) Malba lying near Mandir Marg T-junction.
- vii) Broken central verge seen at many places.
- viii) Desilted malba, cow dung, broken kerb stones lying near Batra T-point.

**D) SURAJ KUND Road:**

- i) Broken kerb stones of Central Verge and footpath be changed.
- ii) On right side, katcha area may be made good.

**E) Mandi Road**

- i) Balance portion of road work to be urgently completed.
- ii) Possibility to be explored for providing Heavy Grade paver blocks on road flanks to streamline two way traffic at viable points.

**F) M Block & Gurudwara Road GK-II**

- i) Camber in road surface not properly maintained. Depression seen/observed.
- ii) Broken kerb stones and depression noticed in footpath.
- iii) Drain work needs to be expedited.

**G) Drain work at Durbal Nath Marg**

- i) Joints of brick work to be filled.
- ii) Line & level to be maintained.
- iii) Malba be cleared.

(जयेश कुमार)

मुख्य अभियंता


अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड़, टी-जंक्शन,नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री एम. के. मलिक, अधीक्षण अभियन्ता, लो.नि.वि.भवन परियोजना परिमंडल एम-44, सुखदेव विहार,मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 3 श्री जय सिंह, कार्यपालक अभियन्ता, रोड़स अनुरक्षण मंडल एम 411 लो0 नि0 वि0, संभू दयाल बाग, ओखला इंडस्ट्रीयल एरिया-3, नई दिल्ली-110020।
- 4 श्री राकेश विज, कार्यपालक अभियन्ता, मंडल एम 441, लो0 नि0 वि0, सुखदेव विहार,मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 5 श्री आर. एस. गर्ग, कार्यपालक अभियन्ता, मंडल एम 442, लो0 नि0 वि0, सुखदेव विहार,मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 6 गार्ड फाईल।



मुख्य अभियंता

अनुरक्षण अंचल- एम 4