

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

नो. 23(25)/CEM-4/PWD/GNCTD/3988



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

दिनांक: - 23 /07/ 2014


Inspection Note

Sub: Re-development of Chandni Chowk Road in between Lal Jain Mandir to Fateh Puri Mosque. (SH: Providing RCC ducts for making services underground).

The site was inspected by Chief Engineer, M-4, PWD on 22-07-14 along with SE, EE (P), AE (P) & JE, M-41, PWD and Sh. S. K. Jain, representative of M/s. Satya Prakash & Bros. Pvt. Ltd.

The following observations were made during inspection :-

1. The last piece of duct placed near crossing of DJB & BSES was having cracks. This piece is rejected and should be removed from the site. EE is directed to ensure that such pieces are rejected at casting yard itself.
2. Last 07 Nos. pieces of ducts were not in line and level. The keys were not inter-locked properly. The top level of ducts were also not matching. These all 07 Nos. pieces should be refixed properly.
3. To ensure the quality of RCC of ducts, rebound hammer should be purchased and testing should be done at site on regular basis.
4. Despite repeated instructions, the progress of work is very slow and it does not appear that the road reach upto first red light from Fateh Puri shall be completed by 27/07/2014. To reduce the inconvenience to general public, the space upto first manhole should be cleared and should be completed with WMM and barricading should also be shifted from this first manhole.
5. The excavated malba should be removed from the site and site where work is being executed should be barricaded leaving space for movement towards footpath.
6. There has been no action by DJB & BSES regarding lines crossing the alignment, the photographs of site should also be sent to DJB & BSES and they may be requested again for action on priority.



(जयेश कुमार)

मुख्य अभियंता

अनुरक्षण अंचल- एम 4

प्रतिलिपि:-


- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियंता, अनुरक्षण परिमण्डल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।

Cont...P-2

- 2 श्री बिजेन्द्र कुमार, अधीक्षण अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण परिमंडल एम-45, 13-वां तल, एम. एस.ओ.भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002.
- 3 श्री एस. एस. सैनी, कार्यपालक अभियन्ता (यो0), परिमंडल एम-41, लो०नि०वि०, अनुरक्षण परिमंडल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 4 श्री संजय वर्मा, कार्यपालक अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण मंडल एम-451, ग्रउन्ड फ्लोर, बहुमंजिला भवन इन्द्रप्रस्थ संपदा नई दिल्ली-110002।
- 5 सहायक अभियन्ता (यो0), परिमंडल एम-41, लो०नि०वि०, अनुरक्षण परिमंडल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 6 गार्ड फाईल।


मुख्य अभियन्ता

अनुरक्षण अंचल- एम 4