

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O.BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

नं०. 23(25) /CEM-4/PWD/GNCTD/ 5254

दिनांक: - 12/09/ 2014

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 inspected the following roads under M-4 along with Sh. G.P. Bansal, SE/M-41 on 12/09/2014. Following observations have been made:-


I. Mathura Road.

- The footpath was found damaged at a number of places:-
 - (i) The paver block were found missing
 - (ii) The footpath was not in level and was found depressed at certain reaches identified during inspection.
 - (iii) Water was found stagnating in the kerb channel at a number of places.
 - (iv) The kerb channel was found blocked at one or two places apparently to provide access to the scooters and motorcycles to the footpath.
- Large quantity of Building material was found stacked at some places & should be removed without any delay.
- Water was found leaking from DJB pipeline near MTNL office and was stagnating in the kerb channel. The matter should be taken up with DJB immediately and also kerb channel and bell mouths should be cleaned for easier flow of water.
- Pot holes were found at regular intervals on the road and should be filled up immediately.
- Road surface was found damaged near
 - (i) Metro pillar 256, 269, 270, 286, 287, 288.
 - (ii) Bus stands at Madanpur Khadar, Sarita Vihar (Toyota building).
 - (iii) Metro Depo Sarita Vihar,
 - (iv) Approach to Okhla Flyover.
- It was observed that central verge is not maintained properly and wild bushes are growing in the central verge.

II. Meethapur/Jaithpur Road

- The manhole covers were found missing at regular interval in nearly the entire stretch of the road. At some places the position is very dangerous and it was directed to take immediate action to replace the missing manhole covers to avoid any accident.
- The kerb channel was found damaged and was also not cleaned properly.

कर्मा प्रती



(जयेश कुमार)

मुख्य अभियंता

अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री संतोष कुमार, निदेशक (उद्यान), लो0नि0वि0, 13वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002
- 3 श्री एस. सी. राघव, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 412, लो0 नि0 वि0, ईश्वर नगर, कालका मोड़, नई दिल्ली-65।
- 4 श्री जी. एस. भाकुनी, उप-निदेशक (उद्यान), लो.नि.वि.उद्यान मंडल एम-414, ईश्वर नगर, कालका मोड़, नई दिल्ली।
- 5 गार्ड फाईल।

कार्य प्रतिक



मुख्य अभियन्ता
अनुरक्षण अंचल- एम 4