

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुसूक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

नं०. 23(25)/CEM-4/PWD/GNCTD/ 5552



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

दिनांक: 23/09/2014

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected roads under Division M-312 along with Shri Mool Chand, Executive Engineer, M-312 on 20/09/2014. Following observations have been made:-

- 1 Proper kerb channel has not been provided on some roads in Sultan Puri and Mangol Puri area. Action should be taken to provide proper kerb channels on all roads.
- 2 Some bell mouths were not properly cleaned.
- 3 Floating material should be cleaned regularly from the drains in Mangol Puri and Sultan Puri area as there is heavy inflow of such material in these colonies.
- 4 One small drain in 'D' Block Mangol Puri was damaged at some places and was open throughout. This drain should be properly repaired and precast covers provided on top.
- 5 A new drain under construction on Road No. 43 was inspected. The contractor was using both old and new bricks and too many brick bats were being used in the masonry work. This part of the drain should be dismantled and constructed again with proper quality new bricks.
- 6 It was observed that the mortar was being mixed directly on road and curing of the recent work done was not visible. The contractor should be strictly directed to adhere to proper curing and mixing mortar in a concrete mixer and pour it on a M.S. or fiberglass sheet rather than directly on road surface. Mortar should preferably be made on service road.
- 7 Barricading and safety tape was not being used at site. Strict instructions should be issued to the contractor not to start the work unless it is properly barricaded.
- 8 Abdul Hamid Marg and other adjacent roads in Shakurpur area where encroachments have recently been removed were also inspected. Directions were issued to expedite the work of reclaiming the road free from encroachments.

(जयेश कुमार)

मुख्य अभियंता


अनुसूक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो०नि०वि०, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एस. के. रामपाल, अधीक्षण अभियंता, एम-31, रोहतक रोड कासिंग, रिंग रोड, पंजाबी बाग, नई दिल्ली।
- 2 श्री मूल चंद, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 312 लो0 नि0 वि0, रोड नं. 43, सैनिक विहार, निकट केशव महाविद्यालय, पीतमपुरा, नई दिल्ली।
- ✓ 3 गार्ड फाईल।


मुख्य अभियंता
अनुरक्षण अंचल- एम 4