कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल— एम 4 राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार) 9वां तल, एम.एस.ओ. भवन, नई दिल्ली— 110002

दूरभाष : 23319795/ फ्रैक्स: 23317728

ਰ0. 23(25) /CEM-4/PWD/GNCTD/



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE –M4 GNCTD, 9TH FLOOR, M.S.O. BUILDING I.P. ESTATE, NEW DELHI- 110002 Phone: 23319795 Fax: 23317728

Email:cepwddelhimzm4@gmail.com

दिनॉक: -24/09/2014

Inspection Note

A meeting with the undersigned was requested by Hon'ble MLA Sh. Kulwant Rana on 22.9.2014. Accordingly the undersigned visited and met Hon'ble MLA and also carried out joint inspection of various roads of his constituency Following observations have been made:-

- 1 Horticulture work in many central verges is either not existing or are not being maintained properly.
- 2 At some places on Sector 17 Road and Dr. K.N. Katju Marg, the new plantations are wilting because of non-watering.
- 3 Central verges also need to be cleaned thoroughly, as there is lot of garbage in them.
- 4 On an internal road of Sector 11, electrical poles are lying on the road side since a long time.
- At many locations on Sector 16 & 17 roads, where the drain work is in progress or just completed, the drain covers have not been placed properly, the junction of drains on road crossings, T-points etc. have not been finished properly and proper ramps have not been provided on the cross streets (where the drain cover level is higher than the cross street level).
- 6 At some locations drains have missing links.
- 7 At some locations, berms have settled resulting in undulating surface.
- 8 On Dr. K.N. Katju Marg and some other roads, grass and vegetation has grown on footpaths.
- 9 At many locations proper frame work of tree pit has not been made, thereby giving it an unpleasant look.
- 10 Drain work in Sector 16 was under progress where plaster work on the existing drain portion is still due to be done.
- 11 It must be ensured that the bricks' quality is as per CPWD specifications and that mortar is made in a mechanical mixer and poured on MS sheet or fibre glass sheet to avoid damage to the existing road and that curing is regularly done for the entire requisite period.
- 12 The portion beyond toe wall on Dr. K.N. Katju Marg which is PWD land is encroached by many jhuggi dwellers and malba is also dumped in this strip of land. A special drive should be started by the Ex. Engineer to clear this land of all unauthorized encroachments as well as malba.

Various discrepancies and defects on many roads were shown by Hon'ble MLA during the above inspection. The undersigned also pointed out the above as well as other defects to the concerned JE, AE and EE, M-312. These defects must be got rectified within 10 days' period, after which SE, M-31 will inspect the above roads for compliance of the instructions, as given during the inspection and also as mentioned above.

(*जयेश कुमार)* मुख्य अभियंता अनुरक्षण अंचल- एम 4 cont.p/2

प्रतिलिपि:-

- 1 सचिव, लो०नि०वि०, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एस. के. रामपाल, अधीक्षण अभियंता, एम-31, रोहतक रोड कासिंग, रिंग रोड, पंजाबी बाग, नई दिल्ली।
- 2 श्री रमेश गर्ग, अधीक्षण अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण परिमंडल एम-35, 6-वां तल, एम. एस. ओ.भवन, इंद्रप्रस्थ संपदा, नई दिल्ली-110002.
- 3 श्री संतोष कुमार, निदेशक (उद्यान), लो०नि०वि०, 13वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002
- 4 श्री मूल चंद, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 312 लो0 नि0 वि0, रोड नं. 43, सैनिक विहार, निकट केशव महाविद्यालय, पीतमपुरा, नई दिल्ली।
- 5 श्री रमेश चंद, कार्यपालक अभियन्ता,लो.नि.वि. विद्युत अनुरक्षण मंडल एम-353, आईएसबीटी फ्लाई ओवर के नीचे, कश्मीरी गेट, दिल्ली-110006.
- 6 श्री राजेन्द्र प्रसाद, उप–निदेशक (उद्यान), लो.नि.वि.उद्यान मंडल एम–314, 13–वां तल, एम. एस.ओ. भवन, इंद्रप्रस्थ संपदा, नई दिल्ली-110002।

🕶 गार्ड फाईल।

अनुरक्षण अंचल- एम 4