

कार्यालय मुख्य अभियंता
लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4
राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)
9वां तल, एम.एस.ओ. भवन,
नई दिल्ली- 110002
दूरभाष : 23319795/ फ़ैक्स: 23317728
न०. 23(25) /CEM-4/PWD/GNCTD/ 1135



O/o THE CHIEF ENGINEER
PWD MAINTENANCE ZONE -M4
GNCTD, 9TH FLOOR, M.S.O. BUILDING
I.P. ESTATE, NEW DELHI- 110002
Phone: 23319795 Fax: 23317728
Email: cepwddelhimzm4@gmail.com

दिनांक: - 13/10/2014

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected roads under Division M-311 along with Shri S.K. Rampal, Superintending Engineer, M-31 & Shri S.P.S. Saini, Executive Engineer M-311 on 10/10/2014.

Following observations have been made:-

(1) Road No. 37 & 40

1. At Junction of Road No. 37 & Ring Road near Prembari Pul, malba has been dumped beyond the ROW of PWD, near the Western Yamuna Canal. It was suggested to construct a toe wall at the end of footpath to act as a view breaker.
2. Under Metro Stations on Road No. 37 & 40, there was no greenery on central verge. EE was directed to write to D.D.(Hort.) to develop greenery at these locations.
3. The damaged plaster of retaining wall constructed on the edge of the footpath towards Canal side should be repaired and then the wall should be properly painted.
4. Manhole frame and covers were above the level of footpath just before Inderlok Metro Station. These manhole cover & frame should be re-fixed matching the level of footpath.
5. In front of Sub Division M-3113 electrical pole (C.C) was lying on footpath this should be removed.
6. Paver blocks fixed on footpath were have settled down at places. These should be repaired.
7. For the matter of removal of posters from Metro Pillars, letter should be written to DMRC.
8. Building material was found lying at Shastri Nagar Bus Shelter, it should be removed.

(2) SWAMI NARYAN MARG

1. The kerb stone at central verge were not fixed properly at places these should be re-fixed. A sample of Kerb stone should be taken by the EE in his presence and get it tested from a reputed laboratory.
2. Painting on kerb stone of central verge was not up to the mark. Painting was peeling off & it should be got attended.
3. Bituminous road were repaired in patches with cement concrete. It was stated by Assistant Engineer M-3113 that the pits were due by DJB for repair of water supply line.
4. CE MZ-4 directed to take photographs and write the letter to DJB for carrying out patch repair on bituminous road with cement concrete.
5. Central parapet of bridge over IFC Department drain was in bad condition. This should be repaired and should be painted.
6. The railing on Central Verge were found tilted and there was gap in between the railings. The railing should be repaired and gap should be filled with old grills.
7. Good earth was being filled in central verge. EE was directed to complete the repair of grill work before completion of Horticulture work.
8. Junction of streets with main road has not finished properly. It should be done in proper way for smooth riding of traffic.
9. Near petrol pump the road has apparently settled down. It should be checked & repaired.
10. The junction of Swami Naryan Marg and Gulab Singh Marg should be improved by repairing of damaged red sand stone. The banners should also be removed at this junction.

(3) SWAMI NARYAN MARG UNDER PASS ROAD

1. The junction of streets with main road were not finished properly. These should be repaired for smooth riding.
2. Malba was lying at places it should be removed.
3. Granite tiles of Swami Naryan Marg were damaged at places these should be repaired.
4. RCC pipe was lying near footpath on the road it should be removed.
5. Electrical poles were also found lying at footpath. These should be removed.
6. Drain cover under underpass should be fixed/placed properly.
7. Reflective tape should be fixed on rotary in front of underpass.

(4) SUNDER LAL JAIN MARG

1. The junction of streets with main road were not finished properly. These junctions should be repaired.
2. The quality of road making was very poor. It should be redone.
3. The finishing of wearing course was not up to the mark. The sample of wearing course be got tested by the EE from a reputed lab.

(जयेश कुमार)
मुख्य अभियंता

अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एस. के. रामपाल, अधीक्षण अभियन्ता, एम-31, रोहतक रोड कासिंग, रिंग रोड, पंजाबी बाग, नई दिल्ली।
- 2 श्री सोमपाल सिंह सैनी, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 311 लो0 नि0 वि0, मुकरबा चौक, जी.टी.करनाल रोड, निकट सीएनजी पेट्रोल पंप, नई दिल्ली।

✓ 3 गार्ड फाईल।

(जयेश कुमार)

मुख्य अभियन्ता
अनुरक्षण अंचल- एम 4