

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुस्क्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

न०. 23(25)/CEM-4/PWD/GNCTD/7089



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

दिनांक: - 16/10/2014

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected roads under Division M-441 along with Shri M.K. Mallick, Superintending Engineer, M-44 & AE/M-4412 on 16/10/2014.

Following observations have been made:-

1. Hans Raj Gupta Marg:-

- (A) **Drain Work:-** Drain work was in progress, following observations were made:-
- One stack of bricks was found to be not satisfactory. This is to be immediately removed from site and only quality bricks are to be allowed to be used in work.
 - At places, brick joints were not filled up properly. It was directed to dismantle such portions of brick work & to redo the same.
 - Paver Blocks & Kerb stones brought to site do not have any marking of the company & are to be rejected. Only good quality paver blocks/kerb stones of approved make are to be used.
 - The excavated materials and malba needs to be removed immediately to avoid any inconvenience to public.

(B) Patch repair work:

- Road opposite M block market has potholes. It was directed that proper demarcation /identification of patch area is to be made before doing patch repair works.
- Patch work needs to be expedited and completed on priority.
- Malba lying along the road should be removed on regular basis.

2. Drain work of Durbal Nath Marg:-

- One stack of bricks at site was not found to be of proper quality & is to be rejected & removed from the site.
- Proper joint fillings in the brick work is to be ensured.
- Excavated materials after refilling needs to be removed as early as possible.

3. Dakshinpuri Marg:-

- RMC work on the berm portion at many places is not up to mark. It needs to be immediately rejected and is to be redone by the agency.

4. Maharishi Balmiki Marg:-

- (i) Works of footpath and central verge are yet to be finished.
- (ii) At few places, road work is yet to be finished.
- (iii) Malba was found lying along the road & should be removed early.
- (iv) Posters/banners have not been removed properly on this road & should be removed on priority.

(जयेश कुमार)
मुख्य अभियंता
अनुरक्षण अंचल- एम 4


प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एम. के. मलिक, अधीक्षण अभियन्ता, लो.नि.वि.एम-44, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 2 श्री राकेश विज, कार्यपालक अभियन्ता, मंडल एम 441, लो0 नि0 वि0, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 3 श्री आर. एस. गार्ग, कार्यपालक अभियन्ता, मंडल एम 442, लो0 नि0 वि0, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।

✓ 4 गार्ड फाईल।


मुख्य अभियंता
अनुरक्षण अंचल- एम 4