कार्यालयः अधीक्षण अभियन्ता,एम-42

लोक निर्माण विभाग, (रा.रा.क्षेत्र दिल्ली सरकार) सुखदेव विहार, मथुरा रोड, नई दिल्ली-110025 दुरभाष / फैक्स संख्या : 26322484/26837368 ई-मेल आई डी : sepwddelhim42@gmail.com



O/o THE SUPERINTENDING ENGINEER, M-42

PWD, (Govt of N.C.T. of Delhi) Sukhdev Vihar, Mathura Road, New Delhi-110025. Telephone/Fax No: 26322484/26837368

E-mail ID: sepwddelhim42@gmail.com

61(1)/CBMC M-42/PWD/2014-15/ 351

Dated: - 2-12-14

INSPECTION NOTE

Inspection note for inspection of Meera Bai Institute of Technology, Maharani Bagh on 02.12.2014.

Today on 02.12.2014 I inspected premises and buildings of aforesaid institute alongwith Sh. Om Prakash, Assistant Engineer, M-423. During inspection it is observed that.

- 1) Large quantity of dismantled unserviceable materials are laying at service centre. Immediate action should be taken for its disposal after observing codal formalities.
- 2) Some dismantled material like section windows and other lying in open area adjoining hostel block. Action for proper storage, and disposal needs to be taken on priority.
- 3) Renovation work in dining hall of hostel block done recently. Surface on top of new fixed tiles not finished properly. Wire gauge of most of windows is damaged. Glass panes are either broken or badly spoiled with splashes of cement/distemper/paint etc. Doors of the dining hall are very shabby with broken wooden bead.
- 4) Exhaust fan in kitchen area is very old and not functioning properly.
- 5) All around the building wild growler of grass and bushes is visible. It needs to be cleaned urgently.
- 6) In all buildings of the Institution, large number of glass panes are either broken or covered with splashes of cement/paint/distemper etc. Immediate attention is needed for hostel block.
- 7) In the hostel block sewer line at one cover is over flowing.
- 8) One old temporary store a having unused old material and bamboos, needs to be removed urgently.
- 9) Pruning of trees being done but cut branches are lying at site.
- 10) Earlier I inspection this institution on 27.10.2014. Action still pending on inspection notes issued vide No. 61(1)/M-42/Inspection/1909 dt. 27.10.2014.

Executive Engineer, M-423 is directed to take immediate action for above listed issues and send report. He may inspect building in detail and initiate action in consultation with institutional authorities.

> Superintending Engineer CBMC M-42, PWD

New Delhi

Copy to:

- 1. The Chief Engineer, M-4, PWD, 9th floor MSO Building New Delhi 110002
- 2. The Superintending Engineer, M-45, MSO Building New Delhi 110002
- 3. The Director Horticulture, PWD 13th floor MSO Building New Delhi 110002
- 4. File No. 23(27)/SE/M-42/PWD/

Superintending Engineer