कार्यालय अधीक्षण अभियंता सिविल भवन अनुरक्षण परिमंडल, एम-43, लोक निर्माण विभाग, 11 वां तल, एम. एस,एस.ओ० भवन, इन्द्रप्रस्थ सम्पदा, लोक निर्माण विभाग मुख्यालय. नई दिल्ली-110002 , दूरभाष: 65103943, 23490488



O/o THE SUPERINTENDING ENGINEER CIVIL BUILDING MAINTENANCE CIRCLE, M-43, 11th Floor, MSO Building, Indra Prastha Estate, NEW DELHI- 110002

PHONE: 65103943, 23490488

Email: sepwddelhim43@gmail.com

संख्याः 23(254)/सि.भ.अनु.परि.एम-43/लो.नि.वि./2014-15/ /80 दिनांक 23 जनवरी 2015

सेवा में,

अन्रक्षण अंचल, एम.-4 लो0नि0वि0, 9वां तल, एम.एस.ओ. भवन, आई.पी.इस्टेट, नई दिल्ली।

विषय: Adoption of Govt. residential Colonies by Department officers under Swachh Bharat Mission.

संदर्भ: आपके कार्यालय का पत्र सं0: 23(Misc.)/CE/M-4/PWD/254 दिनांक 13-01-2015

With reference to above the GLNS Complex at Delhi Gate, Delhi was inspected by undersigned along with EE/AE, M-432 and head of office of GLNS and report in prescribed performa is attached herewith for your kind information.

Encl: As above.

(एस० के० अग्रवाल) कार्भ अधीक्षण अभियन्ता

Copy to following alongwith copy of the report:

- 1. osdswachhbharat@gmail.com
- psud@nic.in
- The Deputy Director, Department of Social Welfare (Estate Cell), GLNS Complex, Delhi Gate, Delhi- 110002 with reference to his letter No. F-54(335)Govt. Acco/EC/DSW/13-14/17842 dated 29-12-2014 for information and necessary action please.
- 4. The Head of GLNS, GLNS Complex, Delhi Gate, Delhi for information & necessary action please.
- 5. The Director (Hort), PWD, 13th Floor, MSO Building, New Delhi for trimming/pruning of the trees in the complex which are causing damage to the buildings.
- 6. कार्यपालक अभियन्ता, सि0भ0अनु0मंडल, एम-432 लो0नि0िव0 नई दिल्ली। to inspect the complex intensively and to carry repairing, painting etc. immediately and submit fortnightly progress/ compliance report.

Encl: As above.

Inspection Report

Name of Officer

Sh. S.K. Agarwal, SE, M-43, PWD.

Date of Inspection

22-01-2015

Place of Inspection

Govt Lady Noyce School, (GLNS Complex), Delhi Gate, Delhi.

Brief Note of Inspection:

GLNS complex inspected along with EE/AE, PWD, Sh. C.L.Roy, Head of Office & other members of GLNS.

The report is as below:

Water Supply:

Water Supply is normal.

Sewage & Sewerage: No problem/complaint was found.

Cleanliness:

No malba/building material was lying in the campus.

Garbage found behind the class room block, which is to be removed by GLNS authority.

Toilets

Damaged/missing fittings are to be replaced. Some of the windows/doors are broken/missing requires repair/replacement. Ceiling requires minor repair in most of the toilets and major repair in 2/3 toilets. Repair works, painting/distempering etc will be carried out by PWD.

School Block G+3 storey block: third floor is lying abandoned and lot of old furniture, rubbish etc. lying outside multipurpose hall, which are to be removed by GLNS authorities. At terrace broken steel Almirah and table are lying, which are to be removed. Necessary repair, painting etc will be done by PWD.

Single Storey Block: Trees on roof require pruning as spouts are chocked and leakages/seepages was observed in room No.6 and toilet. Necessary repair, water proofing, painting etc will be carried out by PWD.

Hostel Block

Boys Hostel: Plaster was peeling in kitchen and will be repaired and painted by PWD. 3rd floor is lying abandoned causing damage to the building and at roof top heaps of old furniture/garbage are required to be removed by GLNS.

Girls Hostel: Condition was reasonable except minor repairs.

Residential Block

One house found to be locked since long. Surroundings are found to be neat & clean and no complaint/defects were observed.

Solar panel installed at terrace is totally damaged and is to be removed.

Photos taken during inspection are attached (4 sheets).

(S.K. Agarwal)

Superintending Engineer