

## कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र(दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728



## O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9<sup>TH</sup> FLOOR, M.S.O.BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

नं. 23(25)/CEM-4/PWD/GNCTD/ 811

दिनांक: - 19/02/2015

## Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 inspected the following Roads under Circle M-41 along with Sh. G.P. Bansal, SE/M-41, Sh. Binod Kumar., EE, M-411, Sh. C. S. Azad, EE, M-412, Shri A. K. Saini, EE/M-413 & Assistant Engineers on 19/02/2015. Following observations have been made:-

### 1. Ring Road from ITO to DND Flyover :-

- At places the road surface is showing the distress signals by alligator cracks. The Executive Engineer was directed to take necessary action and get it repaired after intimating the agency who has done the original work.
- At places kerb stones as well as footpath tiles were dislocated / mis-placed which shall be repaired immediately.
- Pot holes in mastic layer on I. P. Flyover are to be attended immediately.
- DMRC authorities may be contacted for repair of pot holes / depression in the area opposite to Millennium Park handed over to them.
- The road surface near DND Flyover is given very rough riding quality for which necessary action may be taken and if it belongs to DND authority, it may be intimated to them.

### 2. Ring Road from ITO to DND Flyover :-

- Ring Road at various places is showing distressed signals which may be repaired and if time is over necessary action for re-carpeting / strengthening may be taken.
- Maharani Bagh FOB which was damaged by extra height truck was also inspected and it is directed that complete proposal for repair as well as lowering of carriageway along with photographs and recommendations may be submitted.
- At places kerb stones as well as footpath tiles were dislocated / mis-placed which shall be repaired immediately.
- Desilting done in Lajpat Nagar area but the malba has not been removed yet. Necessary action for removal of malba may be taken.

### 3. August Kranti Marg :-

- At places kerb stones as well as footpath tiles were dislocated / mis-placed which shall be repaired immediately.
- At some locations, few potholes are developed on the road, which needs to be filled immediately.

- At some locations, the existing bituminous surfaces are worn out, which need to be corrected on priority.
- On the footpath of road, some paver blocks and earth were lying stacked which require to be removed immediately.
- The road cutting work by Indian Army Signal Company at some stretch was under progress which requires to be completed within the stipulated time period and repaired thereafter.
- At few locations, the planters got damaged for which repair work needs to be done immediately.
- De-silting of storm water drain in this road has not been started which may be started soon.

4. **Street Light :-**

- One Street Light Pole in central verge near Siri Fort Auditorium was found tilted and needs immediate attention

Action taken report may be submitted at the earliest.

कार्यवाही

(जयेश कुमार)  
मुख्य अभियंता  
अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री बिजेन्द्र कुमार, अधीक्षण अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण परिमंडल एम-45, 13-वां तल, एम. एस.ओ.भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002.
- 3 श्री बिनोद कुमार, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 411 लो0 नि0 वि0, जे.बी. टी.टी. मार्ग, एन्ड्रयुज गंज, नई दिल्ली 110049।
- 4 श्री सी. एस. आजाद, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 412, लो0 नि0 वि0, ईश्वर नगर, कालका मोड़, नई दिल्ली-65।
- 5 श्री ऐ. के. सैनी, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 413, लो0 नि0 वि0, भैरो रोड, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 6 श्री संजय वर्मा, कार्यपालक अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण मंडल एम-451, ग्राउन्ड फ्लोर, बहुमंजिला भवन इन्द्रप्रस्थ संपदा नई दिल्ली-110002।
- 7 गार्ड फाईल।

कार्यवाही

(जयेश कुमार)  
मुख्य अभियन्ता  
अनुरक्षण अंचल- एम 4