

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

न0. 23(25) /CEM-4/PWD/GNCTD/180



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

दिनांक: - 23/02/2015

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected various roads under Division M-313 on 23.02.2014 alongwith Shri S.K. Rampal, Superintending Engineer, M-31, Shri Bishambar Dass, EE, M-313 and concerned Assistant Engineers.

The short comings / deficiencies noticed during the visit are as below:-

1. There are patches / deep scratch marks in some portion towards the edge portion of main carriage of Ring Road near Subway at Nigam Bodh Ghat.
2. Alligator cracks and patches of roughness in road top surface noticed throughout in the Ring Road from Nigam Bodh Ghat towards Model Town Mall Road. EE has informed that Ring Road as well as Mall Road is due for Strengthening and P.E. is under process in Division Office. As the condition of road surface is not good and have lots of cracks and roughness thus rubberized paint and patch repair should be done under maintenance work immediately.
3. There is waviness in the main carriageway of Mall Road due to settlement especially from IP College Intersection to Najaf Garh Drain. Thus it is advisable to record initial level of existing surface and P.E. should be supported with the existing road level rather than considering tentative quantity for leveling course and profile correction of road. The P.E. should be submitted on priority.
4. Kerb stones found dislocated near Monastery / Intersection at Metcalf House.
5. Tiles / paver blocks noticed uneven at few locations around ISBT / Nigam Bodh Ghat Area.
6. Kerb channel concrete found damaged near Vidhan Sabha and other locations near ISBT etc. It should be repaired.
7. The grass have grown up on the footpath near Vikas Bhawan. It should be cleared.
8. The Horticulture activity needs to be expedited in this area. Planters / pots etc. have been removed from the central verge in front of Vidhan Sabha but new ornamental planters/ pots etc. have not yet been placed.

9. It was discussed earlier that nursery shall be developed in the wide open central verge area lying unattended since long near Swami Narayan Mandir, but, no action appears to have been taken. Dy. Director (Horticulture) should take immediate action in this regard.
10. At places red sand stone of toe wall cladding was found missing. The portion of toe wall should be finished with plaster instead of stone cladding and near bus stop it can be finished with grit wash.
11. The bell mouths need cleaning at many places between Hanuman Temple (Ring Road) and Vidhan Sabha.

All these points should be attended immediately and ATR should be submitted.



(जयेश कुमार)
मुख्य अभियंता

अनुरक्षण अंचल- एम 4



प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एस. के. रामपाल, अधीक्षण अभियंता, एम-31, रोहतक रोड कासिंग, रिंग रोड, पंजाबी बाग, नई दिल्ली।
- 2 श्रीमति वीणा कांतुते, निदेशक (उद्यान), लो.नि.वि., 13-वां तल, एम. एस.ओ.भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002।
- 3 श्री रमेश चन्द्र, उप-निदेशक (उद्यान), लो.नि.वि.उद्यान मंडल एम-314, 13-वां तल, एम. एस.ओ. भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002।
- 4 श्री बिशमबर दास, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 313 लो0 नि0 वि0, खालसा कालेज के सामने, माल रोड, दिल्ली-110054।
- 5 गार्ड फाईल।



मुख्य अभियंता

अनुरक्षण अंचल- एम 4

