

**कार्यालय मुख्य अभियंता**  
लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4  
राष्ट्रीय राजधानी क्षेत्र(दिल्ली सरकार)  
9वां तल, एम.एस.ओ. भवन,  
नई दिल्ली- 110002  
दूरभाष : 23319795/ फैक्स: 23317728



**O/o THE CHIEF ENGINEER**  
PWD MAINTENANCE ZONE -M4  
GNCTD, 9<sup>TH</sup> FLOOR, M.S.O.BUILDING  
I.P. ESTATE, NEW DELHI- 110002  
Phone: 23319795 Fax: 23317728  
Email:cepwddelhimzm4@gmail.com

नं०. 23(25) /CEM-4/PWD/GNCTD/881

दिनांक: - 24 /02/ 2015

## Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 inspected the Ring Road from ITO Chowk to Timarpur Chowk, S. P. Mukerjee Marg, H. C. Sen Marg and Chandni Chowk Road under Circle M-41 along with Sh. G.P. Bansal, SE/M-41 on 23/02/2015. Following observations have been made:-

### 1. Ring Road from ITO Chowk to Hanuman Setu :-

- The Kerb Stones and carriageway was found settled near Rajghat left turn towards Jawahar Lal Nehru Marg and is to be attended on priority.
- Thermoplastic paint has worn out at various places and is to be got redone by the Agency if it is under maintenance period.
- Toe wall and kerb channel are damaged near Ghata Masjid & should be repaired.
- Lot of grass has come up on the footpath which is to be removed.
- Malba was found along the wall of garden behind Lal Quila which is to be removed.
- Nosing and railing was found damaged at Mangi Bridge & should be repaired.
- The wall of the Mangi Bridge underpass is to be painted.
- On Ring Road Bypass, the carriageway found settled near Pili Kothi. It is to be attended on priority.
- Some small potholes were found on Ring Road Bypass.
- Restoration work near Hanuman Setu is pending for long time & needs to be completed expeditiously.

### 2. S. P. Mukerjee Marg :-

- The Kerb Stone were found dislocated / damaged at places.
- There were undulations on footpath at places which needs to be attended.
- Same potholes were also found which may be repaired immediately.
- The potholes at Lothian Chowk are numerous which may be repaired immediately.

### 3. H. C. Sen Marg :-


- The drain work is very slow. Suitable action as per agreement may be taken against the agency for delayed performance.

### 4. Chandni Chowk Road :-

- MTNL has not started the work. Sh. A. K. Pait, EE-SRD Project, PWD stated that MTNL has finally decided to fix the feeder pillars first and connect it with the old line. The cables will be drawn afterwards. MTNL may start the work by 25-02-15.

- The matter related to providing base plate below the feeder pillar was also discussed and it was decided that base plate may be provided in consultation with EE (Elect.) PWD.
- The drainage of ducts was also discussed and it was directed that final decision may be taken in consultation with SE (Elect.), PWD.
- The progress of work needs to be expedited.

कार्य प्रति

  
(जयेश कुमार)

मुख्य अभियंता

अनुरक्षण अंचल- एम 4


प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री बिजेन्द्र कुमार, अधीक्षण अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण परिमंडल एम-45, 13-वां तल, एम. एस.ओ.भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002.
- 3 श्री ऐ. के. सैनी, कार्यपालक अभियन्ता, रोड़स अनुरक्षण मंडल एम 413, लो0 नि0 वि0, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 4 श्री ऐ. के. पैत, कार्यपालक अभियन्ता, परियोजना मंडल, लो0 नि0 वि0, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 5 श्री संजय वर्मा, कार्यपालक अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण मंडल एम-451, ग्राउन्ड फ्लोर, बहुमंजिला भवन इन्द्रप्रस्थ संपदा नई दिल्ली-110002।
- 6 गार्ड फाईल।

कार्य प्रति



मुख्य अभियंता

अनुरक्षण अंचल- एम 4