

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र(दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O.BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

न0. 23(25)/CEM-4/PWD/GNCTD/882

दिनांक: - 24/02/2015

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 inspected following roads under Circle M-44 along with Sh. M.K. Mallick, SE/M-44 & Shri R.S. Garg, EE/M-442 on 24/02/2015. Following observations have been made:-

(A) Outer Ring Road.

- (i) Large no. of pot holes on side slip road of the Panchsheel flyover were found. The slip road needs to be repaired immedietly.
- (ii) Broken railings/crash barrier is to be repaired.
- (iii) Dumped malba is to be removed from the footpath/burms.
- (iv) Hoardings/banners from flyover needs to be removed immediately.
- (v) Hauz Khas T- Junction not maintained properly.

(B) Phirni Road.

- (i) Damaged footpath is to be got repaired.
- (ii) Pot holes to be got repaired immediately.

(C) West End Marg.

- (i) Land lying vacant on one side of the road may be pertaining to DDA/MCD. Matter is to be taken up with DDA/MCD to maintain it properly as encroachers are creating hazard on road.
- (ii) Culvert work needs to be expedited.
- (iii) Top level of sewer is protruding above road level needs immediate action.
- (iv) The area of land vacated near turning point of Garden of Five Senses may be got widened under the same agreement after examining financial implications & agreement provisions.

(D) M.B. Road.

- (i) Central verge/missing kerb stone to be provided.
- (ii) Malba on central verge is to be removed.
- (iii) Pot holes at various locations to be got repaired.
- (iv) Malba lying where paver block has been replaced needs to be removed immediately.
- (v) Drain work at Khanpur needs to be expedited.

- (vi) Khanpur drain disposal point passes through defence area. Matter is to be taken up with defence authorities for widening of the drain.
- (vii) At some location, central verge concreting is damaged which needs to be repaired.
- (viii) Estimate for remodeling of drain near DJB Pump Station for diverting the storm water/Tigri extension etc may be prepared.
- (ix) Needful action against the persons who are disposing sewage sump in the storm water drain is to be taken up.

(E) Ravi Dass Marg.

- (i) Malba was lying at various location needs to be removed immediately.
- (ii) Pot holes needs to be repaired.

(F) Savitri Cinema Road.

- (i) Damaged footpath is to be repaired.
- (ii) Malba lying at various points needs to be disposed off.
- (iii) Water flowing on road surface is to be checked and drain if blocked may be checked and clear.
- (iv) Central verge work in Alaknanda area is to be taken up on priority.

(जयेश कुमार)
मुख्य अभियंता
अनुरक्षण अंचल- एम 4


प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एम. के. मलिक, अधीक्षण अभियन्ता, लो.नि.वि.एम-44, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 2 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 3 श्री आर. एस. गर्ग, कार्यपालक अभियन्ता, मंडल एम 442, लो0 नि0 वि0, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 4 श्री बिनोद कुमार, कार्यपालक अभियन्ता, रोड़्स अनुरक्षण मंडल एम 411 लो0 नि0 वि0, जे.बी. टीटो मार्ग, एन्ड्रयुज गंज, नई दिल्ली 110049।

✓ गार्ड फाईल।


मुख्य अभियंता
अनुरक्षण अंचल- एम 4