

**कार्यालय मुख्य अभियंता**

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र(दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728



**O/o THE CHIEF ENGINEER**

PWD MAINTENANCE ZONE -M4

GNCTD, 9<sup>TH</sup> FLOOR, M.S.O.BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email:cepwddelhimzm4@gmail.com

न०. 23(25) /CEM-4/PWD/GNCTD/ 3132

दिनांक: - 22 /06/ 2015

**Inspection Note**

The following sites were inspected by Chief Engineer M-4 alongwith SE M-44 and EE/ AE M-441 on dated 22.06.2015 at 10.00 A.M. The following observations were made:

**(A) Savitri Cinema Road :-**

- a) At places, lot of road surface cracked badly. The damaged surface to be repaired immediately.
- b) Footpath and kerb stone scattered/damaged badly at many location from W Block to St. George School and Tara Apartment.
- c) Balance work of central verge should be completed expeditiously.
- d) A lot of malba noticed/observed at various location may be removed immediately.
- e) At 'T' junction noising to be repaired immediately.
- f) The shrubs/plant need ugent attention of DD/M-414.
- g) There is lot of encroachment by illegal parking on both sides of road. The matter may be take up with the Traffic Police and Commissioner (Transport) for legal action & such vehicles may be removed.
- h) Pot hole in the main carriage way should be attended immediately.
- i) It is suggested that plastic sand filled drums with caution reflective tape may be provided at 'T' junction accident & to avoid the damage to noising.
- j) The work of street light on the central verge should also be completed early and no malba should be allowed to be stacked on the road by the Agency.
- k) One damaged electric pole is kept on the footpath. It should be removed immediately.

**(B) Guru Ravi Dass Marg:**

1. Footpath is scattered/broken at various location. It needs to be repaired immediately.
2. Soft encroachment like fruit/vegetable vendor, building material supplier, illegal parking needs to be removed immediately with the help of Police.
3. Road side channel and bell mouth should be cleaned immediately.

**(C) M.B. Road:**

- a. Water logging noticed at 'T' point near Guru Ravi Dass Marg need attention immediately'.
- b. Noising at place broken/damaged badly to be repaired immediately.
- c. Damaged kerb stone of central verge and footpath needs repair immediately.

(जयेश कुमार)  
मुख्य अभियंता  
अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।


**P.T.O.**



- 2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एम. के. मलिक, अधीक्षण अभियन्ता, लो.नि.वि.एम-44, सुखदेव विहार,मथुरा रोड, फलाई ओवर के नीचे नई दिल्ली-25।
  - 2 श्री बिजेन्द्र कुमार, अधीक्षण अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण परिमंडल एम-45, 13-वां तल, एम. एस.ओ.भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002.
  - 3 श्री संजय वर्मा, कार्यपालक अभियन्ता, लो.नि.वि. विद्युत अनुरक्षण मंडल एम-451, ग्राउन्ड फ्लोर, बहुमंजिला भवन इन्द्रप्रस्थ संपदा नई दिल्ली-110002।
  - 4 श्री प्रताप सिंह, कार्यपालक अभियन्ता, मंडल एम 441, लो० नि० वि०, सुखदेव विहार,मथुरा रोड, फलाई ओवर के नीचे नई दिल्ली-25।
- ✓ 5 गार्ड फाईल।



मुख्य अभियन्ता  
अनुरक्षण अंचल- एम 4