




Inspection Report of Chief Engineer (North), PWD on 05-10-2016

Inspection of Arihant Marg, Shah Alam Bandh Road, Outer Ring Road, Burari Road around the Nirankari Complex, Coronation ground was inspected by the undersigned on 05-10-2016 (Wednesday) along with Shri S K Agarwal, Superintending Engineer (North), Shri Bishamber Dass, Executive Engineer (NR), Shri S K Bali, Assistant Engineer, Sub-Division (NR-11). This was with regard to the maintenance work to be done before forthcoming 69th Annual International Sant Samagam to be held from 19 to 21st November, 2016 (Reference : Minutes of the Meeting issued by the Office of the Hon'ble Minister, Home, Urban Development, PWD and Health vide No. Minhealth/6739-62 dated 05.09.2016)

1. **Shah Alam Bandh Marg and Underpass:** - The underpass requires some plaster repairs on the walls, repair of foot-path and painting etc. The surface of the Shah Alam Bandh Road was reasonable except at 2-3 locations where the patch repairing is required. The foot-path, walls are broken at number of places; are to be repaired and painted. EE(NR) informed that the wall along the road belongs to the I&FD, he was directed to take up the matter with concerned Executive Engineer, I&FD for getting these walls repaired immediately.
2. Some Seepage/leakages is also observed. It may be ensured that pump sets remain in working condition to avoid water stagnation in the underpass. EE (Elect.) North is directed to maintain proper and sufficient lighting on all these roads including underpass at Shah Alam Bandh Road for convenience of the public & traffic.
3. **Arihant Marg:** Pot holes, rough patches etc were visible along the road these are to be repaired to have smooth surface for the easy flow of the traffic. The foot-path needs repair and painting.
4. **Burari Road:** The area pertains to the Chief Engineer (East), hence concerned SE / EE may be requested to take repair, painting works etc. on priority.
5. **Outer Ring Road:** The project for improvement of Outer Ring Road is under CPM, F-1 and works are in progress. CPM, F-1 has been requested telephonically to expedite the work, removal of earth, repair of patches, painting etc along the Outer Ring Road for the area under project.
6. EE (NR) informed that the comprehensive repair works of foot-path, drain etc. have already been started in the Sub-Division and work on Arihant Marg and Shah Alam Bandh Marg will be completed on priority by 25.10.2016 i.e. before Diwali.
7. All works of painting of Kerb-stone, road marking which are due since very long time should be completed before Diwali.
8. DD (H) & AD (H) should ensure proper greening of roads i/c regular watering of plants. Pruning of trees should be done wherever required.
9. All are requested to keep all the roads clear, free from dust, garbage or building rubbish and maintenance vans should be ready and well equipped to take emergent repair works during 69th Annual International Sant Samagam period.


Chief Engineer
PWD North Zone
10/10/2016

Copy to :

1. Engineer-in-Chief, PWD, New Delhi for information please.
2. Pr. Chief Engineer (Maint.), PWD (GNCTD), New Delhi for information please.
3. Chief Engineer (East)-M, PWD (GNCTD), New Delhi for information and necessary action on Burari Road.
4. CPM, Flyover Project F-1, PWD (GNCTD), Mukarba Chowk, GTK Road, Delhi-110033 for information and necessary action along Outer Ring Road.
5. SE (North), PWD (GNCTD), New Delhi for information and necessary as detailed above.
6. EE (North), Road Division, PWD (GNCTD), New Delhi for information and necessary as detailed above.
7. EE (Elect.), North Elect. Division, PWD (GNCTD), New Delhi for information and necessary as detailed above
8. Dy. Director (Hort.), PWD (GNCTD), New Delhi for information and necessary as detailed above.
9. Guard File

 
Chief Engineer