



Inspection Report of Chief Engineer (North), PWD on 31-05-2016

The various roads and progress of desilting works on various drains under Shakur Basti Constituency were inspected by Sh. P. B. Singh, Chief Engineer (North)-M alongwith Sh. K. R. Bhandaria, Superintending Engineers (North-West) concerned Executive Engineers, Assistant Engineers, S.O. (Hort.) and others. Following were observed during inspection :

1. It could be seen during inspection that in general the maintenance of the roads is in pathetic conditions inspite of the facts that Roads / Horticulture division are incurring huge expenditure in maintenance of roads.
2. Even after the recent tragic i.e. fatal accident of child in nearby area under the jurisdiction of this division, many of the drain covers are open. There are large gaps in between concrete slabs placed on the drain. Situation is alarming because these drains are also designed as footpath on top. After the accident, cautionary advice and strict instructions were issued by Pr. CE (Maint.) as well as by undersigned but these have not yet be attended.
3. Not a single stretch of the road is in good condition.
4. Even small things which required little expenditure are not being attended. There are lots of bald surface with malba / garbage are littering on these spaces, which are supposed to be maintained green.
5. Some of the defects notices during inspection are listed on below. This is just to give the idea what our Engineers and maintenance staff are performing even after having a large numbers of engineers, huge team of maintenance staff / labour and number of maintenance vans.

Road No.43 Started from Britannia Chowk towards Rani Bagh.

- Grill broken/tilted at places.
- Malba lying in Central Verge at Junction of Road No.44
- Footpath broken at various places

At junction of Balbir Sing Siddhu Marg

- Bell mouth blocked; footpath damaged, Malba lying.
- Precast slab near community centre are uneven, manhole cover tilted
- Footpath broken
- Malba lying in entire central verge
- Footpath Paverblock settled down where howkers are standing.
- Pre Cast Road Slab tilted near urinal

Near Shakurbasti Railway entry

- Kerb stone broken, paver block broken/missing.

Near सामान्य भण्डार

- Footpath broken, Kerb stone broken
- Footpath settled down & covered.
- Around trees edging for kuchaa portion be made surplus paver block lying on footpath.
- Malba laying in kerb channel

Near Ordinance Depot

- Footpath broken
- Footpath settled
- Malba lying in Central verge
- Wild growth on footpath

After junction of Road No.42

- Drain cover tilted
- Grill missing

Near Bhagwan Mahavir Hospital

- Footpath broken
- Central Verge broken
- Kerb Channel not cleaned
- Wild growth on entire service road
- Large gap in precast slab at various places which should be fixed in proper line & level.

Near Petrol Pump

- Different size slab have been fixed instead similar size.
- No. desilting work is going on Road No.43

On service road

- Malba lying in entire stretch alongwith footpath.
- Wild growth on service road.

Near Petrol Pump

- Gap in RCC pre cast slabs
- Uneven level of pre cast slab
- Uneven and gap in RCC slab near Petrol pump
- Videographey of all desilting work of drain be done

In front of Ordinance Depot

- Drain covers uneven
- Footpath broken

From Guru Harkishan Road side

- Footpath broken
- Uneven fixing of Pre cast RCC slabs
- Wild growth on footpath & side
- Kerb Stone missing near Inerprasth Gas Petrol Pump
- At Corner drain cover missing/broken

After Petrol Pump

- Footpath broken
- Kerb Stone broken

Police Line Road from Road No.43

- LHS - C/V broken at entry point
- Kerb channel not cleaned
- One Manhole cover not fixed properly – it is to be lowered down.
- Around trees proper edging to be done
- RHS - Near park Number of Electric RCC poles lying
- Kerb Stone broken near Policy Colony

Parwana Road

- Earth heap lying near trees
- Road to be cleared
- Footpath broken near Axis Bank
- Malba lying along footpath
- Kerb Stone broken
- Footpath covered with Ramps by residents
- Near Mandir Building construction material is lying.
- Footpath occupied by the residents

Parwana Road

- LHS - Unseen slab in front of Houses

Near MSS Hospital

- Footpath entirely encroached by shop keeper/ residents

Junction at Road No.42 (Chander Sekhar Azad Marg.)

- Concrete patch is in uneven shape in carriage way.
- R.C.C. Slab are disturbed
- Kerb stone broken

After Junction

- Construction material lying on Footpath
- Near Sarda Niketan Malba lying

Near Dhalao

- Drain broken, slab displaced
- Kerb stone broken
- Bldg. rubbish & Earth lying
- Bladg. Material lying on Footpath
- Drain slab is open & Cover missing

Parwana Road

- No desilting work seen
- Small heaps of malba/garbage lying
- Near Mitra Vihar
- Bell mouth blocked
- Kerb stone broken

Mahatama Hans Raj Marg

- DJB Work in progress
- Restoration Work needs to be expedited
- Road surface needs patch repair

Near Kejaria Show Room

- Bell mouth/kerb channel blocked
- MCD receipt to be collected from ILFS on day to day basis.
- Schedule of Quantity of all the desilting agreement to be sent to CE office of Division NW R-I & R-II.
- Horticulture in Central Verge single type plants be planted

In front of Sharda Niketan

- Footpath broken

Road No. 42 (C.S. Azad Marg.)

- Desilting material is lying on road side which should be removed.

Superintending Engineer (North-West) and Executive Engineer (North-West) Road-2 to make sure that works are taken on fast track mode and take immediate necessary action for properly securing / covering of nallah, manhole covers within 7 days of issue of this letter and submit the action taken report.

Chief Engineer
PWD North Zone

Copy to :

1. Pr. Chief Engineer (Maint.), PWD (GNCTD), New Delhi for information please.
2. SE (North-West), PWD (GNCTD), New Delhi for information and necessary action please.
3. Director (Hort.), PWD (GNCTD), New Delhi for information and necessary action please.
- 4-5. EEs (North-West) Road-1 & Road-2, PWD (GNCTD), New Delhi for information and remedial action please.
6. Dy. Director (Hort.), North, PWD (GNCTD), New Delhi for submitting the compliance report urgently.

Executive Engineer (Plg.)