

<p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैंसो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613 / 14</p>	 E-mail ID :sepwddelhicnd@gmail.com	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
--	---	--

No. 23(87)/SE/C&ND/PWD/2017-18/

3967

Date: 04-09-2017

INSPECTION NOTE

LG House was inspected on 29.08.2017 along with concerned EE, AE, JE and representative of contractor. During inspection following directions were given:-

A. Inspection of LG House

1. Near Dhobi Ghat, electrical chamber was covered with broken stone slab. It may be replaced with chequered plate/suitable material keeping the electric cable inside the chamber. Action : EE (E)
2. Horticulture/Electrical workers were not wearing PWD uniform while working inside the campus. It may be ensured by DDH/ EE (C)/ EE (E).
3. Any dismantled waste of Civil, Electrical and Horticulture should be removed immediately. Action : All EE/DDH
4. Sun shade is still to be provided to the geysers placed on the roof. This may be done by 10.09.2017. Damaged sheet of old sun shade should be replaced and painting to the stand may be done. Action : EE (C)
5. It was requested by AE(E) to remove mid wall from the AC plant room near PS to LG Chamber for the replacement of AC plant. Action : EE (C)/EE(E)
6. Solar panels are to be provided on 10 No. electric poles. The existing solar water heater system provided on the roof-top of electric sub-station may be replaced with new solar plant of 10KW as per discussion held with PS to LG. Action : EE (E)
7. For the replacement of AC plant near conference room an temporary opening is to be made in the wall of AC Plant room. Action : EE (C)/EE(E)
8. Stagnation of water at main entry of LG House is still to be attended by EE(C). It is getting delayed. Action : EE (C)

B. Inspection of Reception Building

1. RO system of suitable capacity shall be provided on the roof-top along with water cooler. Cool drinking water shall be supplied in the building from this RO system. Insuation to pipes may be done accordingly. Action:EE (E)/EE(C)
2. Insulation of copper pipe is not proper, it needs to be insulated properly. Action : EE(E)

अधीक्षण अभियन्ता
केन्द्रीय एवं नई दिल्ली परिमंडल (एम0)

प्रतिलिपि प्रेषित:-

- 1- The CE (East) M, PWD, New Delhi-110002.
- 2- The OSD to Minister, PWD, 7th Floor, A-Wing I.P Sectt., New Delhi-110002.
- 3- PS to Hon'ble LG, Raj Niwas, Delhi.
- 4- The EE, TH, VS & LG House Divn. (M-321) C&ND DHC&ND/Central Elect. Divn. (M-451) & DDH Divn.(M-214) PWD, Delhi for immediate compliance.
- 5- No. 23(15)/SE/C&ND/PWD/2017-18
- 6- Guard file.

अधीक्षण अभियन्ता