




F. No.61(1)/SE/South East (M)/PWD/2017-18/

3551

dt. 8-9-17


INSPECTION NOTE

1. In continuation to 61(1)/SE/South East (M)/PWD/2017-18/3216 dated.21.08.2017 referred inspection note what improvement has been carried out or complied that may be taken care.
2. The under signed has taken **inspection today 08.09.2017 between 10 to 12:30 PM** and it is seen that whatever point suggested and told during the above inspection are not complied fully. Therefore, please note that **the DBM work on M.B Road between Humdard "T" Point to Karni Singh Shooting Rang** are require improvement because neither it is uniform and not up to the mark, patches are also appears, along the footpath are also to be taken care.
3. **The footpath on SA Marg which is in progress** was told to execute properly and keeping the height of the existing road surface which is not appears to be complied with. Therefore, please note that whatever mentioned in inspection note are to be complied in true letter and sprite for the improvement of the road surfaces as well as for the coming festival season. The signages are also to be taken care which are missing/damaged/tilted immediately. The Pr. CE (M)/E-in-C/ CE(S) all are pressing very hard for the same.


Superintending Engineer
South-East (M), Circle PWD
New Delhi

Copy to:-

1. The Chief Engineer, (South)-M, 7th Floor MSO Building New Delhi.
2. Executive Engineer, South East (M) Road-II, Division PWD, Sukhdev Vihar, New Delhi.


Superintending Engineer