



F. No.61 (1)/SE/South East (M)/PWD/2017-18/ 3755

dt. 26-9-17


### INSPECTION NOTE

Inspection was carried out along with AE Sh. R.K. Khurana and Junior Engineer Sh. K.P. Kaushik of the Savitri Cinema road and Alaknada Road up to Guru Ravidas Marg on dated. 25.09.2017 between 3:30 PM to 4:30PM

1. During inspection it has been observed that at 6 to 7 places on both sides the resurfacing was not up to mark which was already told by JE/AE to EE SER-II and the agency also as told by the AE during inspection. Some work has been incomplete and doing with his own wish and will. Though the RWA and residents of those areas complaining regularly to complete the same at the earliest. Therefore, now the rainy season is over EE SER-II is requested to complete the resurfacing work including removal of defects at the earliest and report for compliance.
2. The conditions of Outer Ring Road are also bad due to creation of potholes next about to Nehru Place flyover side roads and between Nehru Place to Kalka Ji also. Therefore he is requested to pursue the estimate and gets sanction from the competent authority to execute the strengthening/resurfacing of the Outer Ring Road. The festival and tourism season is approaching hence action will be taken on priority.
3. EE SER-I is hereby advised to complete **the signages/beautification work** and other works which has been told time to time by the CE(S), to be carried out on priority, **specially signages works** of all roads.
4. This has been observed that foundation has been made for erecting electrical poles which are not up to the mark and the line level are also not maintained properly the location has been prescribed or given by the JE/AE Electrical. Therefore, the agency is doing with his own wish and will and leaving unfinished work and foundation of Electrical poles. **The malba is laying and the footpath kerb stone are damaging with his own wish and will.** Therefore, JE/AE/EE(E) may please ensure that the foundation has to be in a aesthetic manner and complete the work within a time frame by doing all unfinished work around all foundation. **If the civil work is not finished the recovery has to be made from the agency.** Please ensure that malba has to be removed regularly. EE (E) must ensure that wherever electrical poles are provided **no obstruction for the traffic, public, dispersion of light from the poles affected.** Therefore, he must do regular inspection during the progress of the work and not leaves the work upon the agency only.
5. There is a visit of Hon'ble Prime Minister of India on 17 October 2017 to the Ayurvedic Hospital in Ali Gaon therefore, the Mathura Road should be maintained in a proper manner by carrying out **repair of footpath, kerb stone, central verge painting, removal of unwanted malba, damaged railings/grills/signages etc. all the grills of the central verge and flyover are to be painted** properly which may give nice look also. Similarly the AD (H)/DD (H) are requested to maintain the central verge as well as side pockets along the roads so that no bad



impression goes about the horticulture activity. The SER-II and Horticulture are requested to remove the malba/horticulture waste and do the same on priority immediately. The E-in-C/Pr.CE/CE(S) may take inspection on 13 October 2017 about the up keep route of the Hon'ble Prime Minister of India.

  
Superintending Engineer  
South-East (M), Circle PWD  
New Delhi

Copy to:-

1. The Chief Engineer, (South)-M, 7<sup>th</sup> Floor MSO Building New Delhi.
2. DD(Horticulture), 13<sup>th</sup> Floor, M.S.O Building, I.P. Estate, New Delhi.
3. Executive Engineer, South East (M) Road-I, Division PWD, Ishwar Nagar, New Delhi
4. Executive Engineer, South East (M) Road-II, Division PWD, Sukhdev Vihar, New Delhi.
5. Executive Engineer, South East (M) Electrical Division PWD, Thayagraj Stadium New Delhi.

  
Superintending Engineer