

<p>अभियंता अभियन्ता केंद्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, मैट रोड टी-जंक्शन, रिंग रोड, निकट प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p>	<p>दिल्ली सरकार  E-mail ID :sepwddelhicnd@gmail.com</p>	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
---	--	--

No. 23(15)/SE/C&ND/PWD/2018-19/

2406

Date: 08-06-2018

INSPECTION NOTE

Inspection of LG House was done on 07.06.2018. Inspection was attended by the following officers:-

- (i) Sh. S.K. Mandal, EE, LG House
- (ii) Sh. U.K. Sharma, DDH (East)
- (iii) Sh. Subhash Chand, AE
- (iv) Sh. Narendra, AE (E)

During the inspection, following directions were given:-

A) Gate work**1. Civil work –**

- (a) Connection of old brick wall and new brick wall has not been done properly. Same to be rectified immediately.
- (b) Proper joint filling of brickwork is not being carried. EE/AE to ensure the same. If any work found in this way, same should be dismantled. The progress of gate work needs to be expedited.
- (c) Sample of stone cladding has been approved. Material should be brought at site urgently. Stone jali as per drawing should also be procured in time.

2. Electrical work –

- (a) Guide rail for one gate has been provided. It may be provided to the other gate also keeping the layout and alignment in view.

B) Staff toilet

1. Damaged door/window, shutter etc. may be removed. Renovated toilet should give a new look.
2. Sloping terrace of staff toilet should be painted in terracotta colour.
3. At the steps, granite may be provided.
4. Water from waste pipe of AC is damaging chajja at number of places. AE(E) was directed to provide proper disposal of AC waste water.
5. Work should be completed by 15.06.2018.

C) Meeting with PS to LG

1. Malba needs to be removed from the site of construction of toilet to officers. The work should be completed by 20.06.2018.
2. While making entry from PS room to new toilet, the room should be vacated on holidays and work be carried out accordingly.
3. Rain Water Harvesting – Only one pit needs to be provided in place of 3. Same is to be approved from Delhi Jal Board.
4. Water Recycle – PS to LG mentioned that LG desired to have Water Recycle Unit in LG House. Feasibility study needs to be done in this regard by PWD. EE(C) to take necessary action in this regard at the earliest.

5. Faulty light should be replaced with LED lights wherever required.
6. Conference Room – Light is insufficient. AE (E) suggested that normal tube light should be replaced with LED tube light. It shall be done within a week.

D) Inside LG House campus

1. At number of places, dry leaves/unwanted material was seen in green area, DDH was directed to regularly clean green area and potted plants.
2. In this hot season, special care needs to be given to plants to avoid damage.
3. Back gate of LG House – Boundary wall needs repair at some places and should be white washed wherever it is giving shabby look.
4. Near the main entry in the green area, red sand stone may be provided in the kaccha portion on pedestrian path as Hon'ble LG uses this path in morning walk.

(मुकेश कुमार)
अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The E-in-C, PWD, 12th floor, MSO Bldg., New Delhi-110002.
2. The Pr. CE (East) M, PWD, 3rd floor, MSO Bldg., New Delhi-110002.
3. The EE, THC, VS & LG House Divn.(M-321), PWD, 1-A, Battery Lane, Raj Pur Road, Delhi-110054 – For necessary action as above.
4. The EE, (DHC/ND) Elect. Divn. (M-451), PWD, Ground Floor, MSO Bldg., Delhi-110002 – For necessary action as above.
5. The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091 – For necessary action as above.
6. The ADH, PWD, Horticulture Sub-Div. East-2, Ground Floor, MSO Bldg., New Delhi-110002 – For necessary action as above.
7. Guard File.


अधीक्षण अभियन्ता