कार्यालय कार्यपालक अभियंता (वै०) दक्षिण,वैद्युत मंडल, लो.नि.वि., एम०एस०ओ० भवन, ११वी मन्जिल आई०पी० इस्टेट, नई दिल्ली— ११०००२, दूरभाष नं० २३३१९११२, फैक्स नं०. २३४९०२७८ ई—मेल eeepwddelhim453@gmail.com



O/O THE EXECUTIVE ENGINEER (E)

South Electrical Division, PWD MSO Building, 11th Floor, IP Estate, New Delhi-110002. Phone-23319112, Fax No 23490278 e-mail: eeepwddelhim453@gmail.com

No.: Guard File/South Elect. Divn.,/PWD/2018-19/ 3//)

Dated: 25-11-18

685318

Inspection Note

Inspection of following Subways & Footover Bridges were carried out by the Undersigned on 23.11.2018 alongwith Sh. Lankesh G.P. Mandal AE(E)-III & Sh. Manish Pandey JE(E), Sub-Division-III, PTS Malviya Nagar, New Delhi. The following observation are made:-

- 1. <u>Hyatt Subway-(</u>a) Main Elect. Panel is in very bad shape & needs immediate replacement to avoid any mishappening.
 - (b) 5 Nos. Lights were flickering & needs necessary repairs/replacement.
 - (c) Cables & Loose wires needs proper arrangement for fixing.
 - (d) The defunct Cables, Signboards are to be removed.
 - (e) No Exhaust Fans were Provided.
 - (f) Keys of the pump rooms were not available during Inspection, seen.

AE/JE(E) to check & ensure that pumps are in perfect working Condition and if not necessary arrangement may please be made to make them operational.

- 2. Raj Nagar Subway: (i) Defective light fittings needs to be replaced.
 - (ii) Loose wires to be fixed with proper arrangement.
 - (iii) Pumps were found Non operational, necessary arrangement is to be Made to make them functional.
- 3. Safdarjung Subway: (i) Defective light fittings needs to be replaced.
 - (ii) Loose wires to be fixed with proper arrangement.
 - (iii) Power supply was not found in One Pump.
- 4. Africa Avenue Subway:- (i) Defective light fittings needs to be replaced.
 - (ii) Loose wires to be fixed with proper arrangement.
 - (iii) Drainage arrangement not proper, functioning of pumps to be ensured.

- 5. <u>IIT Gate Subway:-(i)</u> Defective light fittings needs to be replaced.
 - (ii) Loose wires to be fixed with proper arrangement.
 - (iii) Pumps found in working condition.
- (f) Hauz Khas Subway:- (i) Defective light fittings needs to be replaced.
 - (ii) Loose wires to be fixed with proper arrangement.
 - (iii) In One Pump, Non Return Valve is not working & due to which water is coming back in Sump-It needs to be checked & Repair/Replaced.
- (g) Foot Over Bridge:- (i) FOB's at Jia Sarai, Panchsheel Park, IIT, Saket Metro Station Checked & found that all the lifts are working.
 - (ii) Two or three lights are not working at Jia Sarai/IIT Flyover and needs repairs/Replacement.
 - (iii) The lift Operators deputed for Operation of lifts was found available at respective Foot Over Bridges.

In addition to above, it is observed that dismantle material, Defunct fittings/other material are lying in the Elect. Control room/ Pump room in the Subways. The dismantle material needs removal/disposal on prioroity and Cleanliness is to be maintained in the Subways.

AE(E)/JE(E) is directed to ensure compliance of the above observations, Working of Pumps & Exhuast fans in all Subway and submit Action taken report to this office within 20 days.

Executive Engineer(E)
South Elect. Divn..PWD,

Copy for information:-

- 1. Superintending Engineer, South Circle PWD, Sukhdev Vihar, New Delhi.
- 2. Sh. Lankesh G.P. Mandal, Assistant Engineer(E), Sub-Divn.-III, PTS, Malviya Nagar, New Delhi.
- 3. Sh. Manish Pandey JE(E), Sub Division-III, PTS, Malviya Nagar, New Delhi.
- 4. Guard File.

Executive Engineer(E)