



F. No. 61(1)/SE/South East (M)/PWD/2018-19/2856

29/11/2018

Inspection Report

The joint inspection by SE, South East, in the presence of following was done on 22.11.2018 with following observation for necessary action:-

1. Sh. Mukesh Meena, SE, South East.
2. Sh. R.K. Sharma, EE, South East Road-2
3. Sh. Abhay Kumar Mrituanjay, AE, SER-21
4. Sh. Shiv Kumar, AE, SER-22
5. Sh. Sanjay Kumar, AE, SER-23
6. Sh. Rakesh Kumar, AE, SER-24
7. Sh. Abhishek Singh, AE, SER-25

Outer Ring Road from Masjid Moth to Chirag Delhi.

1. The missing/damage drain cover are to be fixed immediately.
2. FOB/Subway needs to be cleaned on regular basis.
3. Damage kerb stone/paver blocks are to be fixed immediately.
4. Railing in central verge is found damage at several places, required to be fixed immediately.

SA Road from Kalkaji Mandir T Point to Govindpuri Metro Station.

1. Damage kerb stone/paver blocks are to be fixed immediately.
2. Drain covers are found damage/missing at several places, the same is required to be fixed.
3. For illegal parking of vehicle, a letter will be written to Delhi Traffic Police for removal of same.
4. Illegal poster/banner will be removed time to time.

Guru Ravi Dass Marg

1. Footpath found damage at various places, same is need to be repaired immediately.
2. Road is found damage at several places due to illegal cutting of road by DJB, the same will be restored immediately and DJB will be requested for deposit of RR Charges.
3. Damage paver blocks required to be fixed immediately.
4. MCD will be requested for removal of illegal hawkers from footpath.
5. Damage/missing drain cover will be fixed immediately.
6. Kerb channel will be cleaned on regular basis.

अधीक्षण अभियंता (दक्षिण-पूर्व)एम,
लोक निर्माण विभाग, (रा.रा.क्षेत्र दिल्ली सरकार) सुखदेव
विहार, मथुरा रोड, नई दिल्ली-110025
दूरभाष/फैक्स संख्या : 26322484/26837368
ई-मेल आई डी : sepwddelhim42@gmail.com



SUPERINTENDING ENGINEER(SOUTH EAST)M
PWD, (Govt of N.C.T. of Delhi)
Sukhdev Vihar, Mathura Road, New Delhi-110025.
Telephone/Fax No : 26322484/26837368
E-mail ID : sepwddelhim42@gmail.com

Hansraj Sethi Marg.

1. The missing/damage drain cover are to be fixed immediately.
2. Damage kerb stone/paver blocks are to be fixed immediately.
3. Kerb channel will be cleaned on regular basis.

Mathura Road/Road No. 13A

1. Need to expedite the progress of both the FOB at Aali Mode and Harkesh Nagar.
2. Drain cover found missing/damage, need to be repaired immediately.
3. Damage kerb stone are required to be fixed.
4. Kerb channel needs to be clean on regular basis.

Superintending Engineer
South-East (M), Circle PWD
New Delhi

1. The Chief Engineer, (South)-M, 7th Floor MSO Building New Delhi.
2. Executive Engineer, South East (M) Road-II Division PWD, Ishwar Nagar, New Delhi.
3. Executive Engineer, South East (M) Electrical Division PWD, Thyagraj Stadium New Delhi
4. The DDH(South) M-114, Horticulture, Divn. MSO Bldg. I.P. Estate, New Delhi for information & necessary action please.

Superintending Engineer