



सं. 23(QC)/लो0नि0वि0 / अनु0परि0(पूर्व)/ 1747

दिनांक: 03.09.2019

**Sub: Inspection of East Road Maint. Sub Divn. M-2121.**

The site of Sub Divn. M-2121 under East Road Maint. Divn. M-212 inspected today i.e. on 03.09.2019 alongwith Assistant Engineer, M-2121. The following observations were found during the inspection.

1. **Seepage in the basement of shop at Shakarpur** - This was the long pending complaints of the owner of the shop. Earlier the site was inspected in the presence of member DJB with other Jal Board Officers, EE M-212, AE and JE. During the inspection, it was decided that the seepage in the basement may be through the drain passing in front of the shop and Executive Engineer was directed to bail out the water from the drain and necessary repair may be taken up to stop the seepage. Even after several reminders from E-in-C PWD, OSD to PWD Minister, nothing concrete has been done. Again on 31.08.2019, message received from Pr. Chief Engineer that the seepage in the basement is still exists. Same day the direction was given to the EE, M-212 to take up the work. To check the progress of the work, the undersigned inspected the drain work alongwith Assistant Engineer on 03.09.2019. The silt from the drain is being taken out and the stagnet water from the drain is being pumping out. AE was directed to do the brick work of the drain alongwith concrete work to the drain flooring and plaster may be done by adding waterproofing compound. This work may be taken up to the adjacent shops also. Work may be completed at the earliest so that there should not be any inconvenience to the shop owners and public.

Necessary Completion report may be submitted to this office after completion of the work.

2. **Iron grill work at Patparganj Road** - The work was inspected alongwith AE. It was found that existing RCC grills are being dismantled completely. AE was directed not to dismantle the existing RCC grills in such a manner. The existing RCC grills may be taken out safely so that may be refixed wherever required. It was also informed by AE that fixing of MS grills at central verge of the Patparganj Road is being done as per requirement under 77 Corridros. AE was advised to check the height of the grills as per requirement under 77 Corridor Scheme. The joints welded may be grinded. Curing may be done for the concrete blocks which were not observed during the site inspection. MS grills may be fixed in proper alignment.

EE may check the quality and quantity of the work. Compliance report of the above two works may be submitted to this office.

अधीक्षण अभियन्ता (पूर्व) एम

**प्रतिलिपि (सूचनार्थ हेतु प्रेषित):-**

1. मुख्य अभियन्ता (पूर्व), लोनिवि अनुरक्षण अंचल, दि.स. तृतीय तल, एम.एस.ओ. भवन, नई दिल्ली।
2. कार्यपालक अभियन्ता, लो.नि.वि. सड़क अनु0 मं0 (पूर्व)/एम 212, रमेश पार्क, नजदीक शकरपुर पुलिस स्टेशन, दिल्ली।
3. वेबसाइट WIMS.
4. गार्ड फाइल।

03/09/2019  
अधीक्षण अभियन्ता (पूर्व) एम