

कार्यालय : कार्यपालक अभियन्ता  
शिक्षा अनुरक्षण मंडल(द. एवं द.पूर्व)  
लो.नि.वि., राष्ट्रीय राजधानी क्षेत्र दिल्ली  
ओखला फ्लाई ओवर के नीचे, मथुरा रोड  
नई दिल्ली - 110065  
दूरभाष : 26928300, फैक्स : 26928301  
ई-मेल : eespwddelhiedm@gmail.com



O/O THE EXECUTIVE ENGINEER  
EDUCATION MAINTENANCE DIV. (S&SE)  
P.W.D., Govt. of N.C.T. of Delhi  
Under Okhla Flyover, Mathura Road  
New Delhi - 110065  
Phone : 26928300, Fax : 26928301  
E-mail : eespwddelhiedm@gmail.com

संख्या: 23(Inspection)/शि.अनु.मं. (द व द-पूर्व)/डी.बी./23-24/ 748

दिनांक: 28/07/2023

### INSPECTION NOTE

The C/o New Govt. School Building on vacant plot at C-Block, Sangam Vihar, New Delhi was inspected today on 28.07.2023 by the Undersigned alongwith Sh. Krishna Kumar Prasad, Assistant Engineer, Sub-Division-III, Sh. Rahul Swami, JE and the concerned contractor. The following observation have been made:-

1. Name of work : C/o New Govt. School Building on vacant plot at C-Block, Sangam Vihar, New Delhi(SH: C/o classrooms, Labs. & Toilets i/c Internal & External Water Supply, Sanitary & Electric Installations, Development of site and firefighting system etc. at C-Block, Sangam Vihar, New Delhi.  
Agreement No. : 29/EE/EMD(South)/PWD/2018-19  
Name of Agency : M/s Devinder Dahiya Infrastructure Pvt. Ltd.  
Estimated Amount : Rs. 32,63,66,314.00  
Tendered Amount : Rs. 30,02,09,671.00  
Date of Start : 17.03.2019

- (i) The work has been physically completed on 05.06.2023.
- (ii) At few locations of verandah, joints were not properly finished, hence required to be rectified.
- (iii) At few location, sand stone fixed in the roof have been found undulated, which required to be corrected. The filling of joints at some locations are not done properly.
- (iv) At some locations, finishing of kota stone flooring is not proper which requires to be properly done.
- (v) Distemping and painting work on doors left the spot and splashes on walls need to be cleaned properly.
- (vi) The painting work on doors have some irregular patches which requires to be done properly.

The Assistant Engineer, Sub-Division-III is directed to take immediate necessary action and get the above defects rectified immediately.

  
Executive Engineer  
Edu.Maint. Div. (S & SE),

Copy:-

1. The Superintending Engineer, Edu. Maint. Circle Unit-II, PWD, Ring Road Bypass Below Flyover, Opp. IGI Stadium Gate No.-9, New Delhi-110002.
2. Assistant Engineer, Sub-Division-III, Giri Nagar, New Delhi for information and necessary compliance report to be submitted on 31.07.2023.

  
Executive Engineer