

**Details of Traffic Engineering Proposals ( Central Verge/Iron Grills, Closure/opening of cuts, Nose protection, Signages, bollards, jerssy Barriers, U-turn sent to PWD during the year 2018**

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
1. /10	Installatiion of jersey barriers on Central Verge of M.B.Road from Khanpur T-Point to Hamdard T-Point	493-498/SO/DCP/T-SR	15-Feb-18	Exe. Engineer, SR-I, PWD, Sukhdev Vihar, Mathura Road	PWD	S-East Distt.	Southern Range	Cv	South Circle	Completed.
2. /13	Installation of iron grills on the central verge from Anuvart Marg T-Point to Lado Saria T-Point	570-74/SO/DCP/T-SR	19-Feb-18	Exe. Engineer SR-1, PWD, Sukhdev Vihar,	PWD	S-East Distt.	Southern Range	cv-iron grill	South Circle	Iron Grills provided.
3. /15	Proposal for installation of Iron Grills on the Central Verge from Anuvart Marg T-Point to Lado Sarai T-Point.	No. 570-574/SO/DCP/T-SR	27-Feb-18	Ex. Engineer, South Road-I, PWD, South Road-II, PWD, JB Tito Marg, Andrews Ganj  Ex. Engineer, South Road-I, PWD, Sukhdev Vihar, Mathura Road, Near Okhla Flyover	PWD	S-East Distt.	Southern Range	Iron Grills	South Circle	Iron Grills provided.
4. /20	Repairing of broken/damaged portion of road dividers	No. 847-53/SO/DCP/T-SR	19-Mar-18	Executive Engineer, South Road-II, (M-411), PWD, JB Tito Marg, Andrews Ganj	PWD	S-East Distt.	Southern Range	repair of road dividers	South Circle	Road dividers repaired. However any

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
										particular location if any be mentioned.
5. /29	Regarding installation of thick iron grills on the Central Verge on SSN Marg	No. 1278-84/SO/DCP/T-SR	03-Apr-18	Executive Engineer, South Road-I, PWD Sukhdev Vihar, mathura Road,Near Okhla Flyover	PWD	S-East Distt.	Southern Range	Iron Grill & C.V	South Circle	Work heldup due to construction activities. Now ban has been lifted and the work yet to be started.
6. /42	Painting of road markings & installation of signages in the area of Hauz Khas Traffic Circle	1723-29/SO/DCP/T-SR	12-Apr-18	Exe. Engineer SR-II (M-411), JB Tito Marg, Andrews Ganj	PWD	S-East Distt.	Southern Range	signages nose protection device, repair of cv, reflectors, rumble strips	South Circle	Signages nose protection device, repair of cv, reflectors, rumble strips provided.
7. /57	Installation of iron grills at central verge on Outer Ring Road from IIT Flyover to Chirag Delhi flyover	2175-81/SO/DCp/T-SR	16-May-18	Exe. Engineer SR-II, M-411, PWD, JB Tito Marg	PWD	S-East Distt.	Southern Range	CV-iron grills	South Circle	CV-iron grills provided.
8. /77	Regarding installation of Iron Grill at the Central Verge of Aruna Asaf Ali	3432-35/SO/DCP/T-SR,	27-Aug.-18	Executive Engineer, SR-II, PWD, JB Tito Marg, Adrews Ganj,	PWD	South	Southern Range	Iron Grill	South Circle	Estimate sent to CE(South)

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
	Marg			New Delhi						office for accord of A/A & E/S.
9. /78	Regarding installation of Jersey Barrier on Central Verge of Ravi Das Marg from Hamdard T-Point to Gali No. 13, Ravi Das Marg in the area of Sangam Vihar Traffic Circle	3498-3508/ SO/DCP/T-SR	29- Aug.- 18	Executive Engineer, SR-I, PWD, Sukhdev Vihar, Mathura Road, near Okhla Flyover, New Delhi	PWD	South East	Southern Range	Jersey Barrier	South Circle	Completed.
10. /79	Regarding fixing of Jersey Barrier on the Central Verge from Khanpur T-Point to Hamdard Red Light after removing iron grills in the area of Sangam Vihar Traffic Circle	3479-84/ SO/DCP/T-SR,	29- Aug.- 18	Executive Engineer, SR-I, PWD, Sukhdev Vihar, Mathura Road, near Okhla Flyover, New Delhi	PWD	South East	Southern Range	Jersey Barrier	South Circle	Completed.
11. /95	Regarding closure of cut at Central Verge opposite Khanpur Depot by putting Jersey barriers	4440-45/ SO/DCP/T-SR	19- Nov-18	Exe. Engineer, SR-I, PWD, GNCTD, Sukhdev Vihar, near Okhla Flyover, New Delhi	PWD	South	Southern Range	closure of cut at Central Verge	South Circle	As per site visit with TI. Closure of cut not feasible.