

राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार
GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

कार्यालय अधीक्षण अभियंता सी.बी.एम.सी. एम - 22, लोक निर्माण विभाग, द्वितीय तल, दिल्ली सचिवालय, नई दिल्ली-110002 फोन नं 23392194	Office of the Superintending Engineer CBM Circle M-22, PWD, Level-2, Delhi Sachivalaya, New Delhi-2 Fax no. 23392191
--	--

सं. 23(क्यू.सी./लो.नि.वि.)/सिंभ०अनु०परि०एम-22/
दिनांक 15/4/14

सेवा में,

मुख्य अधिकारी,
मवन अनुरक्षण अंचल एम - 2,
लो.नि.वि., एम.एस.ओ. मवन,
द्वितीय तल, नई दिल्ली।

विषय: अधीक्षण अभियंता, परिमंडल एम-22 द्वारा किये गये निरीक्षणों का व्यौरा।

संदर्भ: सचिव (लो.नि.वि.) का पत्र सं. PS PWD/119-128 दिनांक 04.03.2014

उपरोक्त विषय एवं संदर्भ में, अधीक्षण अभियंता, परिमंडल एम-22 द्वारा किये गये निरीक्षणों का व्यौरा निम्नान्त है।

क्र. सं.	दिनांक	विवरण	टिप्पणी
1	07/04/14	Inspection of Conference Hall for the office of the District Magistrate (East) at Geeta Colony, Delhi	
2	09/04/14	Inspection of 30 Nos. SPS Class Rooms at Buland Masjid, Jafrabad Ext. & Mandoli Schools	The directions were given to field staff for rectification of defects/short comings pointed out during inspection.
3	09/04/14	Inspection of 20 Nos. SPS type class rooms at Govt. Co-ed Secondary School, Sunder Nagari, Delhi	<p>The following has been found out during checking:</p> <ul style="list-style-type: none"> (a) The original ground level/filled up excavated material was 43cm to 47cm (average 45cm) below top of plinth beam (b) The earth being filled was having brick bats/boulders etc. The same appears as excavated earth. (c) The thickness of P.C.C. 1:5:10 and sand in the corridor (where kota stone flooring work was in progress) was 150mm and 100mm respectively. <p>The directions were given to field staff for prior joint measurement of all the covered up/hidden items.</p>
4	11/04/14	Inspection of D.T.C. Shastadra work	<p>The directions were given to field staff for</p> <ul style="list-style-type: none"> (a) The Executive Engineer should monitor the progress for schedule completion of work. (b) The Executive Engineer should also coordinate with client for release of balance sanction amount. (c) The level of handicapped toilet & electrical rooms should also be raised.

१८/०५/१४
अधीक्षण अभियंता

सी.आनु.परि.एम-22, लो.नि.वि.,
दिल्ली सचिवालय, नई दिल्ली

प्रतिलिपि:-

1. कार्यपालक अभियंता, लो.नि.वि. गं. एम-221, दिल्ली सचिवालय, नई दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित।
2. कार्यपालक अभियंता, लो.नि.वि. मं. एम - 222, मानसरोवर पार्क, शाहदग, दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित।

१८/०५/१४
अधीक्षण अभियंता