राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

कार्यालय अधीक्षण अभियंता		O/o Superintending Engineer
सी.बी.एम.सी. एम - 22,		CBM Circle M-22,
लोक निर्माण विभाग, द्वितीय तल,		Public Works Department, Level-2,
दिल्ली सचिवालय, नई दिल्ली - 110002		Delhi Sachivalaya, New Delhi-2
फोन नं. 23392194		Fax no. 23392191
	071	0: 01/11

सं. 23(क्यू.सी.)/लो.नि.वि./सि.भ.अनु.परि.एम-22/

दिनांक 2/5/14

सेवा में.

मुख्य अभियंता, भवन अनुरक्षण अंचल एम - 2, लो.नि.वि., एम.एस.ओ. भवन, तृतीय तल, नई दिल्ली।

विषयः अधीक्षण अभियंता, परिमंडल एम-22 द्वारा किये गए निरीक्षणों का ब्यौरा।

संदर्भः सचिव (लो.नि.वि.) का पत्र सं. PS PWD/119-128 दिनांक 04.03.2014

उपरोक्त विषय एवं संदर्भ में, अधीक्षण अभियंता, परिमंडल एम-22 द्वारा किये गये निरीक्षणों का ब्यौरा निम्नवत है।

दिनांकः 21/04/2014, 22/04/2014

Internal and external finishing work of G.S.K.V. Khajoori Khas, Delhi (Agency Sh. Aabid Ali) was inspected along with EE & AE. The quality of work needs improvement.

Internal and external finishing work of G.G.S.S.S. Janta Flats, Nand Nagari (Agency M/s M.Y. Construction) and G.G.S.S. F-1, F-2 Block, Nand Nagari (Agency M/s S.S. Builders) were inspected along with EE & AE. The quality of works are not acceptable.

The common deficiencies noticed are as under

- (a) Loose surface is not scrapped.
- (b) The broken edges/surface are not repaired.
- (c) The surface finish not even and smooth.
- (d) The splashes on flooring/skirting/other place were not cleaned.

It was also suggested to incorporate the condition of bulk supply of paint etc. (as per theoretical consumption) before start of work.

दिनांकः 23/04/2014

The work of "20 Nos. SPS Type A.C.R. at Govt. Co-ed Secondary School, Sunder Nagari, Delhi" was inspected along with concerned EE & AE.

The directions were given to field staff for


- (a) Progress of work should be monitored.
- (b) The joints of glazed tiles in the staircase portion should be horizontal/vertical.
- (c) PVC rainwater pipes should be provided.
- (d) Single piece of Kota stone should be use for staircase steps & risers.
- (e) The material as per approved list should be allowed.

दिनांकः 24/04/2014

Inspection of Fire Station at Gokalpuri was carried out along with AE & JE. The client has requested for providing wire mesh shutters in windows & K.O. system.

The directions were given to field staff for

(a) The water supply of newly constructed residential accommodation should be made functional. PBPI/23(miss.)/se



(c) The requirement of wire mess windows in the residential quarters should be examined as per the norms. If required the approval of the same may be obtained.

(d) The Executive Engineer, CBMD M - 221 should submit the consolidated estimate of R.O. System for drinking water supply to the client. The Executive Engineer, M-251 should submit the estimate of electrical to Executive Engineer, M-221.

दिनांकः 25/05/2014

The work of "14 Nos. SPS Type A.C.R. at G.G.S.S.S. Gokalpur, Delhi" was inspected along with EE &

AE.

The directions were given to field staff for

(a) Progress of work is slow, it should be monitored.

(b) The agency has pointed out the non-availability of angles of approved make. The Executive Engineer was asked to check the availability.

(c) The material as per approved list should be allowed.

(d) The development work for proper drainage should also be executed in the sanction issued.

अधीक्षण अभियता सि.भ.अनु.परि.एम-22, लो.नि.वि., दिल्ली सचिवालय, नई दिल्ली

प्रतिलिपिः-

1. कार्यपालक अभियंता, लो.नि.वि. मं. एम-221, दिल्ली सचिवालय, नई दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेत् प्रेषित।

2. कार्यपालक अभियंता, लौ.नि.वि. मं. एम-222, मानसरोवर पार्क, शाहदरा, दिल्ली को सूचनार्थ एवं आवश्यक

कार्यवाही हेत् प्रेषित।

कार्यपालक अभियंता (वै.), लो.नि.वि. वै. मं. एम-251, चौथा तल, एम.एस.ओ. भवन, नई दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित।

न्ता - प्रिअधीक्षण अभियंता