कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4 राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार) 9वां तल, एम.एस.ओ. भवन, नई दिल्ली- 110002

दूरमाषः 23319795/ फ़ैक्सः 23317728

ਰ0. 23(25) /CEM-4/PWD/GNCTD/



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE –M4 GNCTD, 9<sup>TH</sup> FLOOR, M.S.O. BUILDING I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728 Email:cepwddelhimzm4@gmail.com

दिनॉक: 🔑 / /07/ 2014

## **Inspection Note**

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected following roads under M-44, along with Shri M.K. Mallick, Superintending Engineer, M-44 on 19/07/2014. Following observations have been made:-

#### 1. Savitri Cinema Road.

- a) Drain from Savitri Cinema to slip road of flyover to be checked for blockage, if any. The same is to be cleared on priority to avoid water logging.
- b) At three points there is local depression where water was observed.
- c) At one place construction materials were stacked on the R.O.W be removed immediately.
- d) At many places, malba was lying on the road and footpath which should be removed immediately.

### 2. <u>Bipin Chandra Pal Marg</u>

- a. The work of drain is to be expedited.
- b. Malba were seen to be lying at places & should be removed on priority.
- c. At many places work of footpath has been left half done. This needs to be completed to avoid inconvenience to the public.
- d. All old electric poles are still standing, these needs to be removed without any delay.
- e. Electric cables for the street light have been placed near surface at kerb channel, this may be set right & be placed at appropriate level.

# 3. Kalka Public School Road

- a. At Municipal Dhalao, lots of malba and construction waste were stacked. This needs to be removed. The matter may be taken up with MCD for Dhalao cleaning.
- b. At places patch work needs to be done.
- c. No further excavation be done

# 4. Road No. 13

- a. At T-point footpaths and central verge needs to be improved.
- b. Road surface is in shabby position and needs to be improved.
- c. The work of drain completed recently has not been carried out properly & deficiencies should be got rectified on priority.

#### 5. Road No. 14 (Guru Ravi Dass Marg)

- a. Drain cleaning is to be done at places.
- Malba (un-claimed) to be removed.
- c. Unauthorised abandoned vehicles to be removed with consultation of traffic police.

d. At T-Point with Road No.13, improvement of road surface is required.

e. In front of DDA flats two water pipes are passing through strom water drain resulting chocking of rain water flow. The matter may be taken up with DJB to remove the same. If required, by pass may be provided in the drain.

f. Additional pipe of bigger size may be provided from T-Junction towards road No. 13 to

drain off rain water.

(जयेश कुमार) मुख्य अभियंता अनुरक्षण अंचल- एम 4

#### प्रतिलिपि:-

1 सचिव, लो०नि०वि०, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

# प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

1 श्री एम. के. मलिक, अधीक्षण अभियन्ता, लो.नि.वि.भवन परियोजना परिमंडल एम–44, सुखदेव विहार,मथुरा रोड़, फ्लाई ओवर के नीचे नई दिल्ली-25।

2 श्री राकेश विज, कार्यपालक अभियन्ता, मंडल एम 441, लों० नि० वि०, सुखदेव विहार,मथुरा रोड़, फ्लाई ओवर के नीचे नई दिल्ली-25।

🥕 गार्ड फाईल ।

अनुरक्षण अंचल- एम 4