

**कार्यालय मुख्य अभियंता**

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728



**O/o THE CHIEF ENGINEER**

PWD MAINTENANCE ZONE -M4

GNCTD, 9<sup>TH</sup> FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

न०. 23(25)/CEM-4/PWD/GNCTD/1036

दिनांक: - 26/08/2014

**Inspection Note**

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected the **SSN Marg, 100' Foota Road and Outer Ring Road** under the jurisdiction of M-41, PWD on 22-08-14 along Sh. G.P. Bansal, SE CRMC M-41, Sh. Yad Ram Meena, AE, CRMD M-4112 & Sh. Suresh Chand Sharma, JE on 23/07/2014. Following observations have been made:-

**1. 100' Foota Road :-**

- Lot of malba is lying on the berms of 100' Foota Road in kuchha portion. Sh. Y. R. Meena, AE, M-4112, PWD explained that inspite of regular removal of malba from this road, unauthorized dumping of malba is being done in the night regularly. The matter was taken up with Delhi Police and Delhi Traffic Police, but, there is no improvement in the situation. CE, M-4, PWD directed to remove the malba and also directed to take up the matter with the Delhi Police and Delhi Traffic Police.

SE, M-41, PWD informed that this matter of unauthorized dumping of malba is being taken up regularly in Local Works Task Force meetings. He also intimated that matter will be taken up with Joint Commissiner of Police, Delhi Police.

- The Superintending Engineer, M-41, PWD informed that for widening of this road, tenders have been received in the circle office on 20-08-14 and is expected to be awarded after scrutiny in his office.

SE/M-41 was directed to got the work started early in view of representations being received for taking up the work.

- It was observed that kerb stones near bus stand at 100' foota road are damaged, Sh. Yad Ram Meena, AE, M-4112 was directed to replace the same immediately.

**2. SSN Marg :-**

**Name of work :- Strengthening and Improvement of Road by CC Pavement at various locations recently handed by over MCD at SSN Marg Chattarpur, New Delhi.**

**Agency :- M/s. Varun Gupta & Co.**

**Agreement No. :- 84/EE/PWDM-411 /2013-14**

- During the inspection up to Fatehpur Beri, it was found that some panels were cracked and worn out. AE, M-4112, PWD is directed to reject these panels and get it redone. The AE incharge was also directed to identify the panels & enter in the site order book. He should also intimate Executive Engineer the details, so that, he can notify to the contractor through letter also.




- And other side at Fateh Pur Beri. The edge of the connecting road was found very wavy and it was directed that the edge of the concrete road shall be cut to give the smooth alignment of the road.
- The C.C. pavement work in front of Lilly White, Nanda Hospital and Chattarpur also visited and it was found that some panels were worn out, Sh. Yad Ram Meena, AE, M-4112, PWD is directed to reject it and get it redone. The AE incharge was also directed to enter the details of rejected panels in the site order book and intimate Executive Engineer the details so that he can notify to the contractor through letter also.
- The thickness of Mastic Asphalt was found less in some panels at Dera Mor & direction was given to reject & get it redone.

3. **Outer Ring Road :-**

- It was observed that while going to Nehru Place, the carriageway near Savitri Cinema T-Point is damaged and undulating. Executive Engineer may take immediate necessary corrective measures.
- Near Pumposh Enclave, DMRC yard is throwing the water on the main carriageway. The Executive Engineer may take up the matter with DMRC to sort out the issue.  
A big pot hole was also observed on the main locations which may be repaired immediately.
- Malba was found on the main carriageway on Outer Ring Road under T-Point of Lala Lajpat Rai Marg. Executive Engineer is directed to remove the malba immediately to prevent any accident and simultaneously take up the matter with the Delhi Police also.

Action taken report may be submitted at the earliest.


  
(जयेश कुमार)  
मुख्य अभियंता  
अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री जय सिंह, कार्यपालक अभियन्ता, रोड़स अनुरक्षण मंडल एम 411 लो0 नि0 वि0, संभू दयाल बाग, ओखला इंडस्ट्रीयल एरिया-3, नई दिल्ली-110020।
- 3 गार्ड फाईल।

  
मुख्य अभियन्ता  
अनुरक्षण अंचल- एम 4