

अभियंता  
मार्ग, अनुरक्षण अंचल- एम 4  
अध्यानी क्षेत्र (दिल्ली सरकार)  
एल, एम.एस.ओ. भवन,  
नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

न०. 23(25)/CEM-4/PWD/GNCTD/ 1187



O/o THE CHIEF ENGINEER  
PWD MAINTENANCE ZONE -M4  
GNCTD, 9<sup>TH</sup> FLOOR, M.S.O. BUILDING  
I.P. ESTATE, NEW DELHI- 110002  
Phone: 23319795 Fax: 23317728  
Email: cepwddelhimzm4@gmail.com

दिनांक: - 14 /11/ 2014

### Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected following Roads alongwith SE M-44 and EE M-442 on 13.11.2014.

Following observations have been made:-

#### (A) Suraj Kund Road.

- 1 Kerb channel needs to be cleaned.
- 2 A broken steel frame is lying along the road which needs to be removed.
- 3 At few points kerb stones need to be repaired/refixed.
- 4 At some places footpath needs to be repaired.
- 5 The plantation on central verge needs watering & also wire net fencing to protect it from animals.

#### (B) Mehrauli Badarpur Road.

- 1 Lal Kuan FOB is in progress. Till date only foundation work has been completed and 16 pillars of MS pipe have been erected. Balance work is to be expedited.
- 2 At places, kerb stone and footpath tiles are missing or broken which need to be replaced.
- 3 At places, the pavement needs to be repaired.
- 4 Malba from central verge and NMV lane needs to be cleared.
- 5 The plants on central verge needs to be watered at regular interval to keep it green.
- 6 Proper fencing is to be provided on priority to safe guard horticulture works.
- 7 Anti encroachment drive is to be made on regular basis to clear the encroachment.
- 8 If required, additional maintenance van may be deployed to cope up immediate requirements.

#### (C) Guru Ravi Dass Marg.

- 1 The junction of Guru Ravi Dass Marg with Savitri Cinema road needs to be improved.
- 2 There are lot of malba near Sub division office which needs to be removed. In future, this area should be kept clean and not used for collecting malba.
- 3 This road is infested with lot of encroachments. EE should take up regular anti-encroachment drive to clear the encroachment.

(जयेश कुमार)  
मुख्य अभियंता  
अनुरक्षण अंचल- एम 4




प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री एम. के. मलिक, अधीक्षण अभियन्ता, लो.नि.वि.एम-44, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 2 श्री संतोष कुमार, निदेशक (उद्यान), लो0नि0वि0, 13वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002।
- 3 श्री राकेश विज, कार्यपालक अभियन्ता, मंडल एम 441, लो0 नि0 वि0, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 4 श्री आर. एस. गर्ग, कार्यपालक अभियन्ता, मंडल एम 442, लो0 नि0 वि0, सुखदेव विहार, मथुरा रोड़, फलाई ओवर के नीचे नई दिल्ली-25।
- 5 श्री बलवन्त सिंह, उप-निदेशक (उद्यान), लो.नि.वि.उद्यान मंडल एम-414, ईश्वर नगर, कालका मोड़, नई दिल्ली।
- ✓ 6 गार्ड फाईल।

  
मुख्य अभियन्ता  
अनुरक्षण अंचल- एम 4