

## कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

न०. 23(25) /CEM-4/PWD/GNCTD/ 1426



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9<sup>TH</sup> FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email:cepwddelhimzm4@gmail.com

दिनांक: - 19/03/ 2015

### Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected various roads under Circle M-31 on 19.03.2015 alongwith Shri S.K. Rampal, Superintending Engineer, M-31, Shri Praveen Khaturia, EE, M-311, Shri Mool Chand, EE, M-312, Shri Bishambar Dass, EE, M-313 and concerned Assistant Engineers.

The observations made during the inspection are as under for necessary compliance at the earliest:

#### **Ring Road from Punjabi Bagh ROB to Prembari Underpass :**

- 1 The road is having number of potholes and cracks. Necessary action may be taken to repair the potholes as well as carry out rubberized bitumen cracks healing work, wherever longitude or alligator cracks have developed on the roads to avoid further deterioration of the roads.
- 2 The road is also damaged at some places from ROB top to the beginning of Britannia Flyover due to DMRC construction work. The matter may be taken up with highest authority of DMRC to repair the road damaged by them on priority.

#### **Road No. 43 :**

- 1 Patch repair is required on slip road near Britannia Chowk.
- 2 During the excavation work in the island of the junction of Britannia Chowk & Road No.43 by the Metro, the brick walls of the island have been damaged. The same needs to be got repaired properly by the Metro.
- 3 MS railings on the central verge were found tilted/ twisted at some places.
- 4 Malba/garbage is seen almost everywhere in the central verge of the road. The same needs to be cleaned by the PWD Hort.
- 5 Thermoplastic paint on the road, particularly zebra crossings were found faded at places. This should be redone.
- 6 Bus boxes on every bus stand need to be made with yellow thermoplastic paint.
- 7 Kerb stones need to be repainted at places.
- 8 MS railing of central verge needs to be painted.
- 9 Service road is occupied by shopkeepers besides parking on it. The condition of the service road is also deteriorated. The service road needs to be repaired/ strengthened after removal of the encroachments. Matter for removal of encroachments may be taken up with Delhi Police and NDMC.

- 10 Building materials were found stacked on footpath/ berm / road for sale by the building material suppliers at many places. All these materials should be got removed by the building material suppliers. In case they do not remove the material, departmental action may be taken to remove the material.
- 11 There were vegetation/ bushes were found grown on the side of the service road. The same needs to be cut.
- 12 One manhole of the drain on footpath was found missing. The same needs to be placed.
- 13 There was unauthorized parking for buses on the area of the service road opposite Rani Bagh and ahead to Railway Depot.
- 14 Kerb stones of footpath were found damaged near Foot Over bridge.
- 15 Footpath has settled near Balbir Singh Sidhu Marg junction, which should be repaired.
- 16 Bus boxes on the bus stand at every place needs to be made.
- 17 There were minor cuts observed on the road near West Enclave and opposite DCP Office Bhagwan Mahavir Hospital. Necessary repairing is to be done.
- 18 The junction of ORR-26 & Road No.43 required to be repaired/ improved. The matter may be taken up with PM, Fly Over Zone.
- 19 There is MCD dhalao on the service road. Matter should be taken up with MCD for its shifting at appropriate location by them.
- 20 There were lots of unauthorized parking on the road. The matter may be taken up with Traffic Police / Transport Deptt. not to park vehicles on the road.
- 21 Two temporary structures erected in roadside park of DDA, are projecting on the footpath, which should be removed from ROW of the road.
- 22 RCC electrical poles were lying on the road near junction of Outer Ring Road, which should be removed.
- 23 Kerb stones near FOB of Rani Bagh were damaged for 2 – 3m.
- 24 Island near junction of road no. 43 & 44 is not well maintained by Hort. Deptt. Proper greenery should be developed.

**Road No. 42 :**

- 1 Minor Patch repair is required on the junction of Road No.43 & 42.
- 2 One bell mouth was found damaged.
- 3 Tent pandals have made kaccha ramps on the road / footpath for entry into the vacant plots being used for erecting tents. The ramps on the road should be removed.

**Parwana Road:**

- 1 There was malba found stacked on the ROW of the road near House No.443, Deepali. The same needs to be cleaned.
- 2 There was a temporary store constructed on the ROW of the road for the purpose of construction of the house by someone. The same needs to be got removed.

- 3 For the construction of the dispensary the steel were found stacked on the road. The dispensary is being constructed by PWD M-331. The steel needs to be got shifted into the premises of the dispensary.
- 4 There are two MCD dhalaos on the service road near Deepali and Sarswati Vihar. Matter should be taken up with MCD for their shifting at appropriate location.
- 5 Junctions on the road at various places need to be repaired/ improved.
- 6 Intersection of Parwana road with Road No. 44 needs some repairing besides road marking/paint.
- 7 Footpath repair is to be done ending road no.44.
- 8 Sign boards of "No Parking" and not to dump malba on ROW of every road need to be fixed at appropriate locations.
- 9 There were some flower vendors found occupying footpath of the road near Brij Vihar. The same needs to be removed.
- 10 Many houses have encroached on the road by way of constructing ramps to their gates etc., which should be dismantled after giving due notice to the residents.
- 11 A Chinese fast food mobile shop is standing on the road, which should be removed.
- 12 Malba of a new boundary wall being constructed near Kalra Ultrasound, which belongs to the residents, should be got removed by the residents, for which necessary notice should be issued to him.
- 13 Junctions with MCD cross roads should be improved so that there are no potholes and the entry is smooth.
- 14 A small sanitary post is placed outside a Housing Society, which should be removed.

**Mahatma Hansraj Marg:**

- 1 Thermoplastic paint on the road particularly zebra crossings were found faded at places.
- 2 Building materials were found stacked on footpath/berm/ road for sale by the building material suppliers at many places. All these materials should be got removed by the building material suppliers. In case they do not remove the material, departmental action may be taken to remove the material.
- 3 Kaccha portion of berms needs to be made pacca at places.
- 4 There were lot of unauthorized parking on the road. The matter may please be taken up with Traffic Police not to park vehicles on the road.

- 5 Patch repair is needed at the junction of road near ORR for the improvement of the junction. Matter may please be taken up with PM, Flyover Zone.
- 6 There were encroachment on the part of ramps by the various residents. Necessary action for removal of these may be taken up.

**Road No. 44 :**


- 1 Some tile work was going on the footpath. However, it was noticed that the tiles were not having any brand mark. Executive Engineer was directed to stop the work immediately and only approved brands should be allowed.
- 2 Thermoplastic paint on the road particularly zebra crossings were found faded at places.
- 3 Malba/garbage is seen almost everywhere in the central verge of the road. The same needs to be cleaned by the PWD Hort Division, M-314.
- 4 The RCC pipe is lying at the junction of Phirni Road, which should be removed.
- 5 The tyre / puncture repair shop has piled up many tyres on the roadside. The shop should be immediately removed.
- 6 The footpath is damaged near junction of Kali Dass Marg.
- 7 There is a lot of parking opposite Aggarwal City Mall on both sides for which matter should be taken up with Traffic / Transport Deptt.
- 8 Junction of road no. 44 & road no. 41 including service lanes near the junction should be made proper by EE M-311.

**Guru Birja Nand Marg :**

- 1 Kaccha portion of berms needs to be made pacca at places.
- 2 There were unauthorized encroachments on the road near subzi market. Necessary action for removal of the encroachment may be taken up.
- 3 There was a lot of kachra in the planters at the junction of road no. 44. The masonry work was also damaged and there was no greenery in this planter.
- 4 There is a heavy parking menace on this road for which matter should be taken up with appropriate authorities.
- 5 Bricks and building materials were lying on some places, which should be immediately removed.
- 6 The railing was also damaged at some locations, which should be repaired.

**Ring Road under M-313 :**

- 1 Toe wall on Ring Road carriageway from Wazirabad to ISBT at Bela Road 'T' Junction is broken, which should be immediately repaired.
- 2 Potholes and cracks on road from Wazirabad to ISBT Hanuman Setu junction should be immediately repaired.
- 3 A portion of carriageway damaged by DJB and repaired recently has again settled. It should be repaired immediately.

  
(जयेश कुमार)  
मुख्य अभियंता  
अनुरक्षण अंचल- एम 4

**प्रतिलिपि:-**

- 1 सचिव, लो०नि०वि०, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

**प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-**

- 1 श्री एस. के. रामपाल, अधीक्षण अभियंता, एम-31, रोहतक रोड कासिंग, रिंग रोड, पंजाबी बाग, नई दिल्ली।
- 2 श्रीमति वीणा कांतुते, निदेशक (उद्यान), लो.नि.वि., 13-वां तल, एम. एस.ओ.भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002।
- 3 श्री रमेश चन्द्र, उप-निदेशक (उद्यान), लो.नि.वि.उद्यान मंडल एम-314, 13-वां तल, एम. एस.ओ. भवन, इन्द्रप्रस्थ संपदा, नई दिल्ली-110002।
- 4 श्री प्रवीन कथूरिया, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 311 लो० नि० वि०, मुकरबा चौक, जी. टी.करनाल रोड, निकट सीएनजी पेट्रोल पंप, नई दिल्ली।
- 5 श्री मूल चंद, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 312 लो० नि० वि०, रोड नं. 43, सैनिक विहार, निकट केशव महाविद्यालय, पीतमपुरा, नई दिल्ली।
- 6 श्री विशमबर दास, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 313 लो० नि० वि०, खालसा कालेज के सामने, माल रोड, दिल्ली-110054।
- 7 गार्ड फाईल।

  
मुख्य अभियंता  
अनुरक्षण अंचल- एम 4