
कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल— एम 4 राष्ट्रीय राजधानी क्षेत्र(दिल्ली सरकार) 9वां तल, एम.एस.ओ. भवन, नई दिल्ली— 110002

दूरमाष: 23319795/ कैंग्स: 23317728

ਰ0. 23(25) /CEM-4/PWD/GNCTD/



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE −M4 GNCTD, 9TH FLOOR, M.S.O.BUILDING I.P. ESTATE, NEW DELHI- 110002 Phone: 23319795 Fax: 23317728 Email:cepwddelhimzm4@gmail.com

दिनॉक: - 30 /04/ 2015

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 inspected following roads under Circle M-44 along with Sh. M.K. Mallick, SE/M-44, Shri Pratap Singh, EE/M-441 & Shri R.S. Garg, EE/M-442 on 30/04/2015. Following observations have been made:-

(A) Press Enclave Road :-

- At places, lot of road surface noticed cracked badly. The damaged surface is to be sealed immediately with rubberized bituminous work before monsoon.
- 2. Cracked mastic at junction may be replaced by SMA immediately.
- Footpath and side lane damaged badly near Saket Court Mandir Marg T-junction should be repaired immediately.
- At T- junction kerb stone etc. should be repaired immediately.
- Photo of open dhalao opposite Saket Hospital may be sent to MCD for proper disposal of garbage etc.
- 6. At number of places central verge is full of rubbish etc. to be cleaned immediately.
- 7. The shrubs/plant may be cared properly by Horticulture DD M-414.
- There is lot of encroachment near Max Hospital by Gadia Lohar on footpath. The unauthorized encroachment programme may be prepared immediately and action may be taken up accordingly.
- Grill of central verge titled/damaged at number of places to be checked thoroughly and repair immediately.
- Pot hole in the main carriage way at T-junction of PVR road, undulation at T-junction of Basant Kaur Marg in main carriageway to be rectified immediately.

(B) Mandir Marg :-

- Footpath is broken at places, it needs to be repaired.
- Malba of drain may be removed immediately.

(C) M.B. Road:

Central Verge needs to be cleaned and to be made free of rubbish.

(D) Mandi Road:

1. Malba of drain may be removed immediately.

2. Gadaipur water logging: Site was inspected, needful action is to be taken on priority.

(जयेश कुमार) मुख्य अभियंता अनुरक्षण अंचल– एम 4

प्रतिलिपि:--

1 सचिव, लो०नि०वि०, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ संम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

1 श्री एम. के. मलिक, अधीक्षण अभियन्ता, लो.नि.वि.एम—44, सुखदेव विहार,मथुरा रोड़, फ्लाई ओवर के नीचे नई दिल्ली—25।

2 श्री प्रताप सिहॅ, कार्यपालक अभियन्ता, मंडल एम 441, लो० नि० वि०, **सुखदेव विहार,मथुरा रोड़, फ्लाई** ओवर के नीचे नई दिल्ली-25।

3 श्री आर. एस. गर्ग, कार्यपालक अभियन्ता, मंडल एम 442, लो० नि० वि०, **सुखदेव विहार,मथुरा रोड़, फ्लाई** ओवर के नीचे नई दिल्ली–25।

🗚 गार्ड फाईल।

मुख्य अभियंता अनुरक्षण अंचल- एम 4