

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र(दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

नं०. 23(25)/CEM-4/PWD/GNCTD/ 2197



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O.BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email:cepwddelhimzm4@gmail.com

दिनांक: - 1 /05/ 2015

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 inspected following roads under Circle M-41 along with Sh. G.P. Bansal, SE/M-41, Shri Binod Kumar, EE/M-411 & Shri C.S. Azad, EE/M-412 on 30/04/2015.

Following observations have been made:-

1. Ring Road from AIIMS Flyover to Moolchand Underpass.

- Kerb channel and central verge to be cleared from silt and other waste material.
- Kerb stones were coming out from central verge opp. AIIMS hospital gate due to movement of pedestrians. Executive Engineer was directed to get it refixed in proper manner so that these kerb stones may not come out. The EE may take advice from Traffic Police whether zebra crossing may be created along with lowering of central verge at this point.
- Bus boxes may be made immediately by yellow thermoplastic paint at bus stops.
- The condition of central verge at Andrews Ganj flyover is not satisfactory. The wild grass may be removed and central verge may be cleaned properly. Kerb painting has blackened due to smoke of vehicle which may be cleaned and may be painted if required.
- The mastic work at Moolchand underpass is giving away. Possibility of rectification by Micro Surfacing may be explored in the carriageway of the underpass.
- Pot holes were found at the junction of August Kranti Marg on Ring Road which may be filled up.
- The cleaning of kerb channel and bell mouth is required more frequently to prevent blockage of bell mouths during the rains.

2. August Krant Marg :-

- The surface of August Kranti Marg is giving away having alligator cracks at various locations. It was intimated by SE/M-41 that the road surface which was more prone to the pot holes was repaired using rubberized bitumen treatment.
- The condition of junction at Siri Fort complex is bad and it may be treated with stone mastic asphalt.
- SE/M-41 was directed that the matter regarding non-removal of malba by South DMC which was desilted from August Kranti Nallah may be taken up with South DMC.

3. Outer Ring Road :-

- Junction point of August Kranti Marg and Outer Ring Road is required to be improved.
- Road restoration by DMRC near petrol Pump is not done properly. DMRC official be asked to get the restoration of road properly.
- Near FOB Panchsheel location, one portion of main carriageway is depressed which needs to be corrected.
- The cleaning of footpath is required to be improved.
- Under Chirag Delhi Flyover, some old/road dismantled material is lying which requires to be removed or diverted to other office of PWD, if it is required by them.
- The foundation work of foot over bridge at Panchsheel park location is under progress. The foundation work is completed at one side and the excavation of foundation work at other side has just started. The progress needs to be expedited and foundation work at other side should be completed by the May end.
- Executive Engineer was directed that fabrication of steel structure at approved factory may be checked regularly at interval of 5 days & it may be ensured that the installation of columns etc. are started by 15-05-15.

(जयेश कुमार)
मुख्य अभियंता
अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड़, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री बिनोद कुमार, कार्यपालक अभियन्ता, रोड़स अनुरक्षण मंडल एम 411 लो0 नि0 वि0, जे.बी. टीटो मार्ग, एन्द्रयुज गंज, नई दिल्ली 110049।
- 3 श्रीसी. एस. आजाद, कार्यपालक अभियन्ता, रोड़स अनुरक्षण मंडल एम 412, लो0 नि0 वि0, ईश्वर नगर, कालका मोड़, नई दिल्ली-65।
- 4 गार्ड फाईल।

मुख्य अभियन्ता