



384

दिनांक: - 10/05/2015

## Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 inspected following roads under Circle M-41 on 18/05/2015. Following observations have been made:-

### 1. Lala Lajpat Rai Marg.

- Desilted material is lying on footpath while coming from Nehru Place to Moolchand.
- Footpath found damaged at some locations.
- Malba found on footpath at various locations.

### 2. Outer Ring Road.

- Junction of Outer Ring Road /Lala Lajpath Rai Marg needs further improvement, although, repair has been done.
- Malba found on Outer Ring Road near Bhairon Mandir.
- Malba also noticed at other locations on Outer Ring Road.

### 3. M.P. Road.

- Condition of M.P. Road near Fortis Hospital is not satisfactory. DMRC may be asked to improve the road condition.
- DMRC may also be asked to check drainage system. Water logging occurred earlier on this stretch, SE/M-41 to take up the matter with DMRC.

### 4. C.V. Raman Marg.

- Footpath found damaged near Sarai Jullena Village.
- Road condition is bad near Sarai Jullena & at T-junction of Gurudwara Road.

### 5. Mata Mandir Marg.

- Paver blocks found stacked on footpath, but, no work was in progress. SE/M-41 to check & report.

(जयेश कुमार)  
मुख्य अभियंता  
अनुरक्षण अंचल- एम 4

P.T.O.

प्रतिलिपि:-

- 1 सचिव, लो0नि0वि0, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो0नि0वि0, 12वां तल, एम0 एस0 ओ0 भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री बिनोद कुमार, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 411 लो0 नि0 वि0, जे.बी. टीटो मार्ग, एन्ड्रयुज गंज, नई दिल्ली 110049।
- 3 श्रीसी. एस. आजाद, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 412, लो0 नि0 वि0, ईश्वर नगर, कालका मोड, नई दिल्ली-65।
- 4  गार्ड फाईल।

  
मुख्य अभियन्ता