

अधीक्षण अभियंता
परिमंडल एम-41
लोक निर्माण विभाग, दिल्ली सरकार
भैरों रोड, टी-जंक्शन, नियर प्रगति पावर
स्टे0, नई दिल्ली 110002
फोन व फैक्स न. 23379694 / 23379693



आपके सपनों को साकार करते हुए
आपके लिए दिल्ली का निर्माण करते हुए

Superintending Engineer
Circle : M-41
Public Works Department
Govt. of NCT of Delhi
Bhairon Road, T-Junction
Near Pragati Power Station, N.D.-02
Phone & Fax No.23379694/23379693

INSPECTION NOTE

As per directions of the Chief Engineer, MZ-IV, PWD, C.V. Raman Marg & Gurdwara Road under M-412 were inspected by the undersigned on 21.05.2015 (Thursday) along with Shri C.S. Azad, Executive Engineer, M-412, Shri Balwant Singh, DD(H) wherein concerned AE/JE/AD(H) were also present.

Following are observations:

Carriage Way

It is found that number of Commercial Complexes, Residences etc. have constructed ramp within the right of way, without draining arrangement, causing reduction in carriage way width and water is coming directly on the carriage way. Necessary action in this regard should be initiated to prevent damage to the road.

It is observed that Manhole covers on and along the Carriage way are having level difference of about 6" (15cm), which is causing jerk to the vehicles and may cause mishap/accident. At two locations vehicular movement was observed and it is found that leveling of carriage way at these locations is to be taken up immediately (within 24 hours) to avoid mishap.

There is varying gap of about 1-2 meter between carriage way and footpath, filled up with earth, dismantled building material, which is uneven & giving shabby look beside may cause mishap especially for 2-wheelers.

Most of the cross roads to CV Raman Marg were in bad conditions, action is needed so that aesthetic, comfortable & safe roads are available to users.

Foot Path

At number of location Foot Path are not in line and level, few of tiles were misplace. It is observed that drain covers are not placed in line & level and wide gaps were visible, It causes inconvenience to the Pedestrian and are to be set right.

Encroachment

At number of locations along the road/footpath; encroachment (temporary/permanent) is found. Necessary action in association with DTF or as in practice should be initiated for removal of all kind of encroachment within the RoW.

Tree Guards

A number of locations along the road/footpath; steel Tree Guards have not been removed around the fully grown trees, resulting trees are getting damaged. These tree guards should be removed immediately.

De-concretization around trees is not done completely & as per requirement, this should be done.

Contd....2

Malwa

The work of construction of parking by MCD (near village Sarai Jullena) is in progress, but all along footpath heaps of dismantled building material have scattered along the CV Raman Marg. MCD should be pursued to clear the right of way of PWD Road.

Malwa is also found on footpath all along the boundary wall of Escort Hospital, this should be removed and footpath/road be leveled.

Culvert:

Near Bharat Nagar, one culvert/bridge over the drain is existing. The area around Nallah/Drain is to be attended to avoid shabby look & to maintain hygienic conditions along the road side. Culvert may be checked for its structural safety and action for repair/rehabilitation (if required) should be initiated.

Signage

It is found that no proper signages along the road are provided. Road must have all necessary signage like "Warning" (Pedestrian Crossing, School Ahead etc.), "Mandatory" (No Parking, Speed Limit etc.), "Informatory" (Directions, Important building etc.). Necessary action should be initiated keeping in view the IRC/MoRTH specifications, PWD/Traffic Police specifications/guidelines.

Horticulture (Greenary)

Central verge, footpath etc. found to be having barren stretches, requires sapling for new trees, watering etc. to be taken by DD (Hort.); so that greenery can be maintained in the area.

4/2/2015/2015
(एस.के.अग्रवाल)

अधीक्षण अभियन्ता/एम-41

का. प्र. ४

सं०: 23(15)एम-412/सि.रो.अनु.परि. एम-41/लो.नि.वि./2015.16/ 1716 दिनांक: 21 मई 2015

प्रतिलिपि:

1. मुख्य अभियन्ता, अनुरक्षण अंचल, एम-4, लो.नि.वि., नई दिल्ली को सूचनार्थ।
2. श्री सी०एस० आज़ाद, कार्यपालक अभियन्ता, एम-412, लो.नि.वि., नई दिल्ली को उपरोक्त सभी बिन्दुओं पर आवश्यक कार्रवाई हेतु।
3. उप-निदेशक (उद्यानन), एम-414, लो.नि.वि., नई दिल्ली को उपरोक्त उद्यान संबंधी बिन्दुओं पर सूचनार्थ एवं आवश्यक कार्रवाई हेतु।

4/2/2015/2015
अधीक्षण अभियन्ता

का. प्र. ४