

| | | |
|--|--|---|
| <p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैंसो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p> |  <p>E-mail ID : sepwddelhicnd@gmail.com</p> | <p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Fax No.: 23379693</p> |
|--|--|---|

No. 23(87)/SE/C&ND/PWD/2017-18/ 3433

Date: 31-07-2017

सेवा में,

1. कार्यपालक अभियन्ता (वै०),
के.एवं.न.दि. वैद्युत मंडल (एम-451),
लो.नि.वि., नई दिल्ली-110002
2. कार्यपालक अभियन्ता,
तीस हजारी, वि०सभा० एवं एल.जी. हाऊस
मंडल (एम-321), लो.नि.वि., दिल्ली-110054

Sub: Inspection of LG House by CE, East.

LG House was inspected by CE, East on 27.07.2017. During the inspection following directions were given:-

1. Flower Pot provided in LG House should be of same size as far as possible. Record of colouring of pot should be maintained.
2. Unwanted plants needs to be removed at no. of locations shown to DDH.
3. 13 Nos. workers are working in LG House. DDH to provide duty assigned to them.
4. Chequered tiles provided in the garden have been dislocated. These needs to be refixed.
5. Some of the plants are infected with insects and sunburn. DDH should take preventive measures in this regard.
6. Flower bed area should be well defined with symmetry for different plants.
7. Electrical panel board was seen near CCTV control room. The panel should be provided with proper sign board.
8. EE (E) mentioned that 25 nos. poles are to be erected and the work shall be completed in all respect by 06.08.2017. EE (E) to ensure the same.
9. For proper lighting by poles, pruning needs to be done by DDH.
10. DDH / EEs to ensure best workers are posted in the LG House.
11. It was suggested to provide herbal garden in the LG House. DDH to explore the feasibility.
12. Meeting was taken up with PS to LG. In the meeting, following directions were given:

- (i) There should be no seepage in the lift.
- (ii) Peripheral path of the main garden needs extra attention as Hon'ble LG use it in the morning. Footpath should be in proper shape and plants should be properly maintained.
- (iii) Toilet for drivers – Proper maintenance & finishing needs to be done by EE, LG House Division.
- (iv) Repair of unused internal lift was discussed. PS to LG stated that the matter would be discussed after November, 2017.
- (v) It was intimated that work of reception shall be completed by 31.08.2017.
- (vi) Water overflow was observed in the porch recently. EE to check the sewer / drain pipes for blockage and proper repair to manhole.
- (vii) Approval to furniture work in reception bldg. is to be expedited by LG House Sectt.

अधीक्षण अभियन्ता
केन्द्रीय एवं नई दिल्ली परि० (एम०)

प्रतिलिपि प्रेषित:-

1. Guard file.
2. DDH- for Mr.

अधीक्षण अभियन्ता