



F. No. 23(18)/SE/South East (M)/PWD/2017-18/ 2913


dt. 13/7/17

INSPECTION NOTE

Inspection done by Superintending Engineer (South East) M, dated.13.07.2017 time 1.30 to 2.30 PM.

- Inspection of drainage system as well as beautification/repair of footpath etc has been discussed while doing the inspection along with Assistant Engineer Shri. G.A. Khan, and Junior Engineer, S.K. Singh as well as the agency also.
- While doing the inspection of Nehru Nagar drainage system JE/AE in front of agency are directed that the finalisation should be done on priority and extra malba are to be removed so that during current rainy season the water logging should not occur in this area. The finalisation of footpath as well as site is to be looking finally aesthetically good. JE/AE may please be taken care that site should be cleared properly.
- The drainage improvement at Sarai Kale Kha near Sun dial Ring Road is also to be finalise earlier. The position of the footpath is also to be kept in such a way that no traffic should ply on the footpath, to prevent the manholes. However the work should be completed within 15 days so that during the current rainy season the drainage/water logging affected should not be there.
- The repair of the footpath from Ashram to Sarai Kale Kha and Sarai Kale Kha to Ashram on the other side are to be taken care properly no such small small patches etc. should be left out as shown at site. The final finalise of footpath, kerb stone/channel/till/stones are also should be given look aesthetically directed and uniform. The small wall is also to be made where unwanted elements are putting malba. Therefore, the ugly look is to be prevented as shown at site near DND approach coming to the Ring Road.
- The beautification work doing below Andrew Ganj Flyover are to be completed at the earliest by having a meeting at Executive Engineer level with electrical and horticulture counterpart also so that while completing the beautification work should not look ugly because this road is belongs to the Hon'ble L.G.
- It is also requested that the desilting work is going on as second cycle has informed during the inspection hence care should be taken for plying the maintenance van so that kerb channel, manholes as well as hip of the small small silt/kachara should not be visible at site otherwise the same will again goes to the drains and creates the water logging problem.

The Independence Day is coming very soon therefore whatever tenders already awarded or in hand for painting /cleaning or other miscellaneous work are to be taken care regularly so that up to the 15th August the main Ring Road or BRT Road must look pleasant.


Superintending Engineer
South-East (M), Circle PWD
New Delhi

Copy to:-

1. The Chief Engineer, (South)-M, 7th Floor MSO Building New Delhi
2. The EE, SER-I, Ishwar Nagar, New Delhi.
3. AE, Sh. G.A. Khan SER-I.


Superintending Engineer