अधीक्षण अभियन्ता

केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैंरो रोड टी—जंकशन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली—110002 फोन न:—23378613/14



E-mail ID: sepwddelhicnd@gmail.com

Superintending Engineer

Central & New Delhi Circle
Public Works Department
Govt. of NCT of Delhi,
Bhairon Road T-Junction, Ring Road,
Near Pragati Power Station,
New Delhi-110002

Phone No.: 23378613 / 14

Date: 12-12-2017

No. 23(15)/SE/C&ND/PWD/2017-18/ 5653

INSPECTION NOTE

Sub: Inspection undertaken by CE(East) on 08.12.2017 under C&ND Road Division.

CE(East), PWD carried out Inspection of C&ND Roads on 08.12.2017 along with the following officers:-

- 1) Sh. Mukesh Kumar, SE (C&ND).
- 2) Sh. S.K. Garg, EE(C&ND) Road.
- 3) Sh. T.P. Singh, DDH (East).
- 4) Sh. V.K. Garg, AE(C&ND) Road.
- 5) Sh. D.N. Gupta, AE(E), DHC&ND/Central (M-451).
- 6) Sh. Shyam Singh, ADH (East).

During inspection, following directions were given:-

- Minor Engineering Works to be undertaken for NCAER Area should be properly surveyed along with proposed scheme. Matter is to be referred to UTTIPEC for their approval.
- Azad Bhawan Road Area may be surveyed and proposed scheme for development of footpath may be submitted to CE for perusal.
- 3. I.P. Flyover Greenery may be improved in the central verge. Dustbin needs to be provided. There should be no encroachment in the area and no unauthorised person should be allowed to stay in Pump House or in any other area. Sign board may be provided mentioning "Silence Please", "Do not litter". Details of malis, security guard, pump operator etc. should be displayed at Notice Board at Pump House. Notice to temple is to be given.
- Art installation at I.P. Flyover and Gulab Vatika Focussed light may be provided.
- Samta Sthal Footpath needs repair. Missing drain cover to be provided. DJB
 over flow was observed which may be got attended. Green area near tree may be
 provided with edging.
- Service road near Samta Sthal Malba needs to be removed. Practice of making mortar on road should be stopped.
- 7. JLN Marg Footpath needs to be repaired.
- Hanuman Setu Painting of kerb stone is being done without cleaning the surface.
- ISBT U-turn Footpath/toe wall needs repair, proper sign for merging traffic should be provided at U-turn.

- 10. Subway extension Curing not being done properly. Bulging of RCC wall was observed due to improper shuttering. The work needs to be expedited so that additional lane could be made available to traffic. Existing gantry sign board needs to be redesigned to accommodate additional lane. Completion programme is to be submitted by EE/Contractor.
- 11. Salimgarh underpass Encroachment of shop should be removed.
- 12. Old Iron Bridge Sign board and road marking are missing.

The above directions may be followed in a time bound manner. ATR may be submitted by 18.12.2017.

्रिअधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

- 1. The CE (East), PWD, 3rd floor, MSO Bldg., New Delhi-110002.
- 2. The EE, (C&ND) Road Divn. (M-413), PWD, New Delhi-110002.
- The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091.
- The EE, (DHC/ND) Elect. Divn. (M-451), PWD, Ground Floor, MSO Bldg., Delhi-110002.
- The AE (C&ND) Road Sub-Divn.-I, Road Sub-Divn.-II & Road Sub-Divn.-III, ADH(C&ND), PWD.
- 6. Guard file.

अधीक्षण अभियन्ता