

| | | |
|---|--|--|
| <p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैरो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p> | <p>दिल्ली सरकार  E-mail ID :sepwddelhicnd@gmail.com</p> | <p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p> |
|---|--|--|

No. 23(15)/SE/C&ND/PWD/2017-18/ 318

Date: 22-01-2018

सेवा में,

1. कार्यपालक अभियन्ता,
के.एवं.न.दि.सड़क मंडल (एम-413)
लो.नि.वि., भैरो रोड टी-जंक्शन,
रिंग रोड, नई दिल्ली-110002
2. उपनिदेशक (उद्यान)
उद्यान मंडल पूर्व (एम-214),
लो.नि.वि., द्वितीय निजामुद्दीन ब्रिज,
एन.एच.-24, ईस्टर्न एपरोच, दिल्ली-91

विषय : Inspection carried out by SE, C&ND on 22.01.2018 relating to ASEAN preparation.

Inspection was carried out by undersign on 22.01.2018 along with the following officers:-

- 1) Sh. S.K. Garg, EE(C&ND) Road.
- 2) Sh. V.K. Garg, AE(C&ND) Road.
- 3) Sh. Shyam Singh, ADH (East).

During the inspection, following directions were given for immediate compliance:-

- 1) Malba/loose material was seen near Bhairon Marg X-ing and in the stretch from Bhairon Marg to I.P. Metro Station. It may be removed immediately.
- 2) Sign board at I.P. Flyover is damaged. May be repaired urgently.
- 3) **Nosing at the start of Ring Road Bypass** – It has been repaired recently. Kerb stone needs to be painted.
- 4) **Gulab Vatika to Shanti Van left side service lane** – Malba and unwanted material needs to be removed. Toe wall has been damaged for movement from main road to service road. Entry to service road from Nishad Raj Marg is blocked by Traffic Police. This matter should be taken up by EE, C&ND Road with the Traffic Police so that there is smooth movement from main road to service road. Damaged brick work needs to be repaired.
- 5) Some pole/sign board pedestals are still to be white painted.
- 6) **Raj Ghat X-ing**
 - a) Milestone may be provided with details as discussed at site immediately.
 - b) Central verge needs to be cleaned immediately. ADH and AE(C) to take action.
 - c) Island near Raj Ghat X-ing – Due to watering to plants, soil has come on the pavement. This needs to be stopped immediately by Horticulture Unit and the area should be cleaned.
 - d) PWD stickers are coming out from the potted plants. It may be properly fixed.

7) Ring Road Bypass

- a) Kerb stone painting in progress. Central verge still incomplete. The work needs to be completed on war footing by diverting the resources.
 - b) Near cremation ground – Heap of earth/malba seen which may be cleared immediately.
 - c) Horticulture work needs to be improved in the Ring Road Bypass area.
- 8) Grass to be removed on the footpath from Bhairon Marg to Raj Ghat X-ing, especially along the I.G. Stadium, Ring Road.
- 9) Hanuman Setu to Sanyas Ashram –
- a) Road marking still incomplete. Kerb stone painting still incomplete. These may be completed immediately.
 - b) Loose kerb stone are seen near Monestry, Buddh Vihar and a number of places in the stretch. These may be fixed urgently.
 - c) Pot holes seen below ISBT Flyover on Ring Road.
- 10) For ASEAN preparation, EE, C&ND Road should divert resources from other Sub-Divisions for water tanker, maintenance van and vacuum cleaning machine so that ASEAN preparation is completed in time.

Above directions may be complied within 24 hours.

(मुकेश कुमार)

अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The CE (East), PWD, 3rd floor, MSO Bldg., New Delhi-110002.
2. The EE, (DHC/ND) Elect. Divn. (M-451), PWD, Ground Floor, MSO Bldg., New Delhi-110002.
3. Guard file.

अधीक्षण अभियन्ता