

राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार Govt. of NCT of Delhi लोक निर्माण विभाग अधीक्षण अभियंता फ्लाईओवर-5

**Public Works Department Superintending Engineer** Flyover- 5



रिंग रोड पलाईओवर के नीचे, विपरीत आई0 जी0 स्टेडियम गेट नं0 9, नई दिल्ली-110002 Under Ring Road Bypass Flyover, Opp. of IG Stadium Gate No.9, New Delhi-110002

Email:

सं0 23(12) / अधी.अभि. / एफ-5 / लो.नि.वि. / 2024-25 / 30% (भ)

दिनांक 2.0/05/2024

## निरीक्षण नोट

कार्य का नाम:

Repair and Rehabilitation of GokulPuri Flyover Delhi. (SH: -Replacement of Bearings and Expansion joint and repair of Bearing Pedestal).

Agency:-

Hercules Structural System Pvt. Ltd

Agreement No.

04/EE/F51/PWD/2022-23

Tendered Cost:-

Rs. 6,61,62,169/-

Date of Start (Stipulated):

07.10.2022

Date of Completion (Stipulated):

06.04.2023

% Progress:

37%

Inspection of above work was carried out by the undersigned on 15.05.2024 along with below PWD official & agency representative.

## **PWD Side:**

1. Sh. Ajay Narwal

Executive Engineer, F-51

2. Sh. Bharat Kumar

Assistant Engineer, F-512

3. Sh. Neeraj Kumar Pandey

Junior Engineer, F-512

## Agency Side:

Sh. Himanshu Pal,

Project Manager, (M/s Hercules Structural Systems Pvt. Ltd.)

2. Sh. Sumit Jha,

Site Engineer, (M/s Hercules Structural Systems Pvt. Ltd.)

During the inspection, it is found that bearing replacement work is in progress on Span no. 2 of carriageway of Gokulpuri Flyover from Ghaziabad to Wazirabad. The following points were discussed: -

- 1. The Agency is asked to deploy the more manpower to complete the rehabilitation work on given time.
- 2. Agency to adhere to all safety guidelines as per agreement, CPWD Works Manual, Safety codes, Good structural engineering practices & as issued by GNCTD vide No. 4(60)/23-24/PWD-II/Roads dated 11.07.2023. Responsibility of any violation shall be executing agency & EE should take action as per guidelines for any violation.

- 3. It is directed that all measures are to be taken to control air pollution. Dust control measures be implemented at site along with sufficient anti-smog gun. Responsibility of any violation shall be of executing agency & EE should take action as per guidelines for any violation.
- 4. Target date of completion has not been achieved. EE is directed to take action as per this office order No. 23(Works)/ अधी. अभि. / एफ-5 / लो.नि.वि. / 2023-24 / 278 दिनांक 03.10.2023 & 23(Works) अधी. अभि. / एफ-5 / लो.नि.वि. / 2023-24 / 278 दिनांक 19.03.2024 with in one week of issue of this inspection note.

०\ अधिक्षण अभियंता, फ्लाईओवर परियोजना परिमण्डल एफ-5

## प्रतिलिपि सूचनार्थ प्रेषित:-

1. मुख्य अभियन्ता (फ्लाईओवर), लो.नि.वि., चौथा तल, एम.एस.ओ.भवन, नई दिल्ली।

2. **कार्यपालक अभियन्ता**, एफ—51, रिंग रोड़ फ्लाईओवर के नीचे, विपरीत आई.जी.आई. स्टेडियम गेट नं. 09, नई दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेतु।

3. M/s Hercules Structural Systems Pvt. Ltd., प्रथम तल, प्लॉट नंबर 2, एफ.आई.ई, पटपड़गंज इंडस्ट्रीयल क्षेत्र, दिल्ली–110092 ईमेल:– sales@herculesindia.com

० \ अधीक्षण अभियंता