PEDESTRIAN ACCIDENT PRONE ZONE - 2017

S	S.NO	S.No. as per list	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN
	1	25	DND FLYOVER	South East Circle	Pertain to DND Express authority.

ACCIDENT PRONE ZONE – 2017

S.NO	S.No. as per list	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN
1	33	ASHRAM CHOWK	South East Circle	ashram chowk is handed over to DMRC
2	36	HOTEL CROWN PLAZA MAA ANAND MAI MARG	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately.
3	41	SARITA VIHAR FLYOVER	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately
4	43	DND FLYOVER	South East Circle	Pertain to DND Express authority.
5	51	KALINDI KUNJ	South East Circle	Pot hole filled up, estimate for widening of road is in progress, footpath also
6	57	ICD TUGLAKABAD	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately
7	61	JAITPUR MORE	South East Circle	Pot hole filled up, estimate for widening of road is in progress, footpath also improved.
8	66	LAJPAT NAGAR FLYOVER	South East Circle	All expansion joints are in order now
9	67	AIIMS	South East Circle	Re-surfacing of AIIMS flyover already completed
10	88	GOVINDPURI METRO STATION	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately.
11	98	SARITA VIHAR METRO STATION	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately.
12	105	PRAGATI MAIDAN GATE NO. 5	South East Circle	Pertain to C & ND
13	106	APOLO HOSPITAL	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately.
14	111	TOLL PLAZA BADARPUR	South East Circle	Pertain to NHAI
15	117	MOOL CHAND	South East Circle	Jersey barriers has been placed as per Traffic Police directions
16	119	SURAJ KUND CROSSING MB ROAD	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately.
17	133	ROUND ABOUT OKHLA ESTATE	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately.
18	135	OKHLA MORE	South East Circle	Road condition improved, pot hole whenever noticed filled up immediately.