

Details of Traffic Engineering Proposals (Central Verge/Iron Grills, Closure/opening of cuts, Nose protection, Signages, bollards, jerssy Barriers, U-turn sent to PWD during the year 2018

| Sl. No. | SUBJECT | SENT VIDE NUMBER | DATE | ADDRESSED TO | AGENCY CONCERNED | DISTT | RANGE | REMARKS | Office | PWD |
|---------|--|-------------------------|-----------|---|------------------|---------------|----------------|--------------------|--------------|-----------------------|
| 1. /1 | Regarding repair of dividers at Indra Mohan Bhardwaj Marg, C.R. Park, Greater Kailash-II | No. 46-51/SO/DCP/T-SR | 04-Jan-18 | The Executive Engineer, SR-I, PWD, Sukhdev Vihar, Mathura Road, Near Okhla Flyover | PWD | S-East Distt. | Southern Range | Repair of dividers | South Circle | |
| 2. /10 | Installatiion of jersey barriers on Central Verge of M.B.Road from Khanpur T-Point to Hamdard T-Point | 493-498/SO/DCP/T-SR | 15-Feb-18 | Exe. Engineer, SR-I, PWD, Sukhdev Vihar, Mathura Road | PWD | S-East Distt. | Southern Range | Cv | South Circle | Completed. |
| 3. /13 | Installation of iron grills on the central verge from Anuvart Marg T-Point to Lado Saria T-Point | 570-74/SO/DCP/T-SR | 19-Feb-18 | Exe. Engineer SR-1, PWD, Sukhdev Vihar, | PWD | S-East Distt. | Southern Range | cv-iron grill | South Circle | |
| 4. /15 | Proposal for installation of Iron Grills on the Central Verge from Anuvart Marg T-Point to Lado Sarai T-Point. | No. 570-574/SO/DCP/T-SR | 27-Feb-18 | Ex. Engineer, South Road-I, PWD, South Road-II, PWD, JB Tito Marg, Andrews Ganj Ex. Engineer, South Road-I, PWD, | PWD | S-East Distt. | Southern Range | Iron Grills | South Circle | Iron Grills provided. |

| Sl. No. | SUBJECT | SENT VIDE NUMBER | DATE | ADDRESSED TO | AGENCY CONCERNED | DISTT | RANGE | REMARKS | Office | PWD |
|---------|--|-------------------------|-----------|--|------------------|---------------|----------------|--|--------------|--|
| | | | | Sukhdev Vihar, Mathura Road, Near Okhla Flyover | | | | | | |
| 5. /20 | Repairing of broken/damaged portion of road dividers | No. 847-53/SO/DCP/T-SR | 19-Mar-18 | Executive Engineer, South Road-II, (M-411), PWD, JB Tito Marg, Andrews Ganj | PWD | S-East Distt. | Southern Range | repair of road dividers | South Circle | Road dividers repaired. However any particular location if any be mentioned. |
| 6. /29 | Regarding installation of thick iron grills on the Central Verge on SSN Marg | No. 1278-84/SO/DCP/T-SR | 03-Apr-18 | Executive Engineer, South Road-I, PWD Sukhdev Vihar, mathura Road,Near Okhla Flyover | PWD | S-East Distt. | Southern Range | Iron Grill & C.V | South Circle | Iron Grill & C.V. P.E. In process. |
| 7. /42 | Painting of road markings & installation of signages in the area of Hauz Khas Traffic Circle | 1723-29/SO/DCP/T-SR | 12-Apr-18 | Exe. Engineer SR-II (M-411), JB Tito Marg, Andrews Ganj | PWD | S-East Distt. | Southern Range | signages nose protection device, repair of cv, reflectors, rumble strips | South Circle | Signages nose protection device, repair of cv, reflectors, rumble strips provided. |

| Sl. No. | SUBJECT | SENT VIDE NUMBER | DATE | ADDRESSED TO | AGENCY CONCERNED | DISTT | RANGE | REMARKS | Office | PWD |
|---------|--|-----------------------|-------------|---|------------------|---------------|----------------|----------------|--------------|--|
| 8. /57 | Installation of iron grills at central verge on Outer Ring Road from IIT Flyover to Chirag Delhi flyover | 2175-81/SO/DCp/T-SR | 16-May-18 | Exe. Engineer SR-II, M-411, PWD, JB Tito Marg | PWD | S-East Distt. | Southern Range | CV-iron grills | South Circle | CV-iron grills provided. |
| 9. /77 | Regarding installation of Iron Grill at the Central Verge of Aruna Asaf Ali Marg | 3432-35/SO/DCP/T-SR, | 27-Aug.-18 | Executive Engineer, SR-II, PWD, JB Tito Marg, Adrews Ganj, New Delhi | PWD | South | Southern Range | Iron Grill | South Circle | Estimate sent to CE(South) office for accord of A/A & E/S. |
| 10. /78 | Regarding installation of Jersey Barrier on Central Verge of Ravi Das Marg from Hamdard T-Point to Gali No. 13, Ravi Das Marg in the area of Sangam Vihar Traffic Circle | 3498-3508/SO/DCP/T-SR | 29- Aug.-18 | Executive Engineer, SR-I, PWD, Sukhdev Vihar, Mathura Road, near Okhla Flyover, New Delhi | PWD | South East | Southern Range | Jersey Barrier | South Circle | |
| 11. /79 | Regarding fixing of Jersey Barrier on the Central Verge from Khanpur T-Point to Hamdard Red Light after removing iron grills in the area of Sangam Vihar Traffic Circle | 3479-84/SO/DCP/T-SR, | 29- Aug.-18 | Executive Engineer, SR-I, PWD, Sukhdev Vihar, Mathura Road, near Okhla Flyover, New Delhi | PWD | South East | Southern Range | Jersey Barrier | South Circle | Completed. |

| Sl. No. | SUBJECT | SENT VIDE NUMBER | DATE | ADDRESSED TO | AGENCY CONCERNED | DISTT | RANGE | REMARKS | Office | PWD |
|---------|---|-------------------------|------------|---|------------------|-------|----------------|---------------------------------|--------------|---|
| 12. /95 | Regarding closure of cut at Central Verge opposite Khanpur Depot by putting Jersey barriers | 4440-45/ SO/DCP/T-SR | 19- Nov-18 | Exe. Engineer, SR-I, PWD, GNCTD, Sukhdev Vihar, near Okhla Flyover, New Delhi | PWD | South | Southern Range | closure of cut at Central Verge | South Circle | Site visit with TI has been fixed to check the feasibility. |