## **Details of Speed Calming Measures Proposals (Pending/Execution) sent to PWD during the year 2018**

SI. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status	Present Status	Office	Status
1. /13	Painting of road markings & installation of signages in the area of Saket Traffic Circle - Near Asian Market on MB Road Road safety features (SCM, signages, road markings, reflectors, nose protection devices etc.)		12-Apr-18	Not Installed	Not Installed	South Circle	Work awarded but not started due to NGT pollution guideline. Now ban has lifted and work will be started soon.
	Installation of speed calming measures in front of sarvodaya Bal Sr. Sec. Vidyalaya, Qutub, Mehrauli (SCM)		12-Apr-18	Not Installed	Not Installed	South Circle	To location at which the speed breaker to be made is in the jurisdiction of SDMC.

SI. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status	Present Status	Office	Status
3. /22	Installation of speed calming measures on internal road connecting Balbir Saxena Marg to Hauz Khas		20-Apr-18	Not Installed	Not Installed	South Circle	SCM- Table top exist at T- junction of Balbir Saxena Marg and Hauz Khas Road.
4. /50	Installation of speed calming measures in front of Sarvodaya Bal Sr. Secondary Vidyalaya, Qutub, Mehrauli		09-Oct-18	Not Installed	Not Installed	South Circle	Rumble strips provided.
5. /66	1.Raise the height of the railing on the Central Verg from IIT to Jia Sarai on the Outer Ring Road to atleast 6 feet  2.Shift/remove or cut the trees on the servie road near SDA Markert, Outer Ring Road  (Regarding speed calming measures on Mehrauli-Mahipalpur Road near Traffic	SO/DCP/T-SR,	11-Dec-18	Not Installed	Not Installed/Not required	South Circle	<ol> <li>Tender called.</li> <li>Pertains to Horticult ure.</li> </ol>

SI. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status	Present Status	Office	Status
	signal of Mehrauli-Mahipalpur Road and Church –only in the subject –speed calming measures not installed)						