


# दिल्ली सरकार प्रमुख अभियंता, लो०नि०वि०,





Toll Free Complaint No. 1800 11 0093 वेंबसाइट: http://pwd.delhigovt.nic.in ई—मेल: pwdhqdelhi@gmail.com/dppwdhqdelhi@gmail.com

सं0ः लो०नि०वि० / प्रमुख अभि / कार्य / 2017 / 3 75 9

दिनांकः 10.08.2017

विषयः Minutes of First Monday Review Meeting.

The first Monday review meeting was held on 08.08.2017 under the Chairmanship of Engineer-in-Chief wherein following were present:

## S/Shri:

1. A.K. Garg Pr. CE (M)

Surendra Singh Chief Engineer (Health) M
 Umesh Mishra Chief Engineer (North) M
 Manoj K. Mohoia Chief Engineer (South) M

5. Pradeep Gupta Chief Project Manager (Health) Project

6. M.K. Mallick Chief Project Manager (Edu.) M

7. Sanjeev Rastogi Pr. Director (E&W) & Chief Project Manager (OP) 8. Manu Amitabh Pr. Director (NI) & Chief Project Manager (Housing)

9. Ravi Kant
Superintending Engineer (Project)
10. Mukesh Kumar
Superintending Engineer (C&ND)
11. S.K. Jain
Superintending Engineer (South-East))
12. Mohan Lal
Superintending Engineer (North)
Superintending Engineer (West)

14. Mathura Prasad Superintending Engineer (South West)
 15. Mukesh Meena Superintending Engineer (South)

16. Vijay Kumar Superintending Engineer (South)

17. Manoj Kumar Director (Hort)

18. Jaswant Singh
 19. Krishan Pal Sharma
 20. Vijay Kumar
 Dy. Director (Hort) North
 Dy. Director (Hort) South
 Dy. Director (Hort) East

The Engineer-in-Chief, PWD pointed out that there is no progress/improvement in the maintenance works of PWD despite regular and repeated instructions to improve the maintenance of PWD, particularly, in the roads section. The instructions and minutes of the Ist Monday Review Meetings are issued for improvement in the maintenance works, but no concrete action has been taken by the field staff, particularly, in the following areas:

### 1. Greening of Roads:

Hon'ble Lt. Governor of Delhi has described that PWD roads are the face of the Delhi and greening on PWD roads should be at par with the green area maintained by DIAL at Air-port. Action Plan should be prepared to meet the expectation of the Hon'ble Lt. Governor.

#### 2. Road Repairing Work:

Pot holes should be filled by Pot hole filling machine instead of manual repairing. Despite repeated instructions, no action has been taken in this regard. It was decided in the last

meetings that pot holes should be filled with automatic pot hole repair machine, but no action has been taken. There is a need for taking immediate action in this regard.

## 3. Improvement of Roads:

Wherever there is a need, the riding quality needs improvement along with repairs to the kerb stone, median, foot paths, road markings and corrections in the signages.

- 4. Sh. Surender Singh, Chief Engineer (Health) Maintenance has intimated that they have implemented mandatory bio-metric attendance for outsourced staff. But bio-metric attendance is not implemented in other offices for outsourced staff, despite clear and repeated instructions by this office. Henceforth, all attendance should be bio-metric attendance and payment for outsourced staff should be made on the basis of bio-metric attendance in all the offices of the PWD.
- 5. All the points mentioned in the last Minutes of the Meeting are to be complied by the concerned offices and compliance report of the same is to be submitted to this office.

This issues with the approval of the Engineer-in-Chief, PWD.

(संजीव रस्तोगी) निदेशक(कार्य एवम् स्थापना)

सेवा में

- 1. प्रधान मुख्य अभियंता (अनुरक्षण), लो.नि.वि, 12वां तल, बहु—मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली—02।
- 2. प्रधान मुख्य अभियंता (परियोजनाएं), लो.नि.वि, 12वां तल, बहु—मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली—02।
- 3. मुख्य अभियंता(उत्तर), लो.नि.वि, 5वां तल, बहु-मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली-02।
- 4. मुख्य अभियंता(दक्षिण ), लो.नि.वि, 7वां तल, बहु-मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली-02।
- 5. मुख्य अभियंता(पूर्व), लो.नि.वि, तीसरा तल, बहु-मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली-02।
- 6. मुख्य अभियंता(स्वास्थ्य) अनुरक्षण, लो.नि.वि, दूसरा तल, बहु-मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली-02।
- 7. मुख्य अभियंता(शिक्षा), लो.नि.वि, पहला तल, बहु—मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली—02।
- 8. मुख्य परियोजना प्रबंधक (एफ-1), लो.नि.वि, मुकरबा चौक, जी.टी.करनाल रोड़, दिल्ली-33।
- 9. मुख्य परियोजना प्रबंधक (एफ-2), लो.नि.वि, सरायं काले खां, रिंग रोड़, दिल्ली-13।
- 10. मुख्य परियोजना प्रबंधक (एफ-5), लो.नि.वि, भैरों रोड़, टी जंकशन, प्रगति पावर स्टेशन, नई दिल्ली-02।
- 11. मुख्य परियोजना प्रबंधक (स्वास्थ्य), लो.नि.वि, ६वां तल, बहु—मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली—02। 12. मुख्य परियोजना प्रबंधक (गृह), लो.नि.वि, 13वां तल, बहु—मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली—02।
- 13. मुख्य परियोजना प्रबंधक (शिक्षा), लो.नि.वि, दूसरा तल, बहु-मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली-02।
- 14. मुख्य परियोजना प्रबंधक (अन्य), लो.नि.वि, 13वां तल, बहु—मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्ली—02।
- 15. अघीक्षण अभियन्ता (स्वास्थय), लो.नि.वि, , नई दिल्ली।
- 16. अघीक्षण अभियन्ता (सी एण्ड एन डी), लो.नि.वि, , नई दिल्ली।
- 17. अघीक्षण अभियन्ता (दक्षिण), लो.नि.वि., नई दिल्ली।
- 18. अघीक्षण अभियन्ता (दक्षिण-पूर्व), लो.नि.वि, , नई दिल्ली।
- 19. अघीक्षण अभियन्ता (पूर्व), लो.नि.वि, , नई दिल्ली
- 20. अधीक्षण अभियन्ता (उत्तर)— लो.नि.वि, नई दिल्ली), लो.नि.वि, , नई दिल्ली
- 21. अघीक्षण अभियन्ता (दक्षिण), लो.नि.वि, नई दिल्ली), नई दिल्ली
- 22. अघीक्षण अभियन्ता (परियोजना), लो.नि.वि, नई दिल्ली।
- 23. निदेशक (उद्यानि) लो.नि.वि, नई दिल्ली।
- 24. उपनिदेशक (उद्यानि) (उत्तर) लो.नि.वि, नई दिल्ली।
- 25. उपनिदेशक (उद्याान) (दक्षिण) लो.नि.वि, नई दिल्ली।
- 26. उपनिदेशक (उद्यानि) (पूर्व) लो.नि.वि, नई दिल्ली।

निदेशक(कार्य एवम स्थापना)