

कार्यालय मुख्य अभियंता  
भवन परियोजना अंचल बी-2  
लो०नि०वि० (दिल्ली सरकार)  
दूसरा तल, एम.एस.ओ. भवन  
आई.पी. एस्टेट, नई दिल्ली -2  
दूरभाष-23319153,23724394  
फैक्स-23324794



O/o Chief Engineer  
Building Project Zone B-2  
PWD (Govt. of NCT of Delhi)  
2<sup>nd</sup> Floor, MSO Building  
I.P. Estate, New Delhi - 2  
Ph.:23319153, 23724394  
Fax:23324794  
E-mail: cepwddelhibpz2@gmail.com

**INSPECTION REPORT OF SARVAGYA KR. SRIVASTAVA, CHIEF  
ENGINEER IN RESPECT OF BUILDING PROJECT ZONE, B-2**

**DATED 02.4.2014**

Chief Secretary, GNCTD along with Pr. Secretary(Finance), Secretary (PWD), Secretary (Health) inspected the campus of GTB Hospital with the officers of Department of Health and PWD. He also held a meeting with all concerned regarding improvement of functioning of GTB Hospital and other facilities.

He directed that newly constructed Diabetic Centre should be made ready in all respects for inauguration by 1<sup>st</sup> of May, 2014. Similarly, newly constructed 500-bedded hospital should also be spruced up and made ready for occupation by the same date. PWD has already submitted for air-conditioning of top four floors of newly constructed hospital.

After the inspection of the laundry block, Chief Secretary directed that entire laundry facility should be upgraded including upgradation of the building.

The shed constructed for new Gynecology OPD needs to be extended and the surrounding area needs to be further improved.

All the roads and footpath which have been dug up for laying various services should be repaired and brought to original shape by 30<sup>th</sup> April, 2014.

Landscaping of all the green area should be completed and potted plants should be tended/replaced. Benches may also be provided in the green areas for patients and their attendants.

Appointment of consultant for installation of medical gas pipeline in the newly constructed 500-bedded hospital needs to be expedited.

Road maintenance unit of PWD need to repair the footpath and drain on both sides of the entry gate and provide railing to prevent its encroachment.

**(Sarvagya Kr. Srivastava)  
Chief Engineer (F-1)**

E-mail to:

1. CE, M-2 for information and necessary action regarding road outside the gate please.
2. PM, B-22 & B-23
3. Director (Hort.)