


**PROJECT MANAGER
FLYOVER PROJECT CIRCLE F-13
PUBLIC WORKS DEPARTMENT, GOVT. OF DELHI
MUKARBA CHOWK, G. T. KARNAL ROAD,
DELHI - 110033**

Ph: 011-27691871, Fax No.: 011-27691971

E-Mail: pmpwddelhif13@gmail.com



F. No. 23(28-I)/PM/FPC/F-13/PWD/2014/ 2316


Date: - 24-9-14

Inspection Note

Sub: - Inspection Note for the work of "Comprehensive Development of Corridor (Outer Ring Road) between Madhuban Chowk to Mukarba Chowk."

Went to Dheerpur casting yard and reviewed the casting of spine segment today i.e. on 22.09.2014. EE, F-131 and Project Manager of M/s. ITD were present. Took the round of casting yard and it was observed that the certain improvements in the shutter surface of spine segment, where reinforcement dowels is coming out in regular segment / pier segment, as suggested during my earlier inspection and inspection dated 25.08.2014, have not been done. It is regretted to point out that once the directions have been issued by undersigned, EE should have ensured its compliance. It was now strictly directed that these improvements should be done immediately, maximum within one week and compliance should be reported to this office. EE was also directed to increase his input at site to closely monitor these issues. It would have been appreciated if EE himself would have suggested certain improvements apart from complying the direction of undersigned which is not the case.

Then, inspected the casting of crash barrier fascia panels. EE was directed to ensure that surface of fascia panels is smooth and damaged panels, if any, should be rejected out-rightly.


**Project Manager
Flyover Project Circle F-13, PWD** 22/9

Copy to:-

- (1) Chief Engineer, Flyover Project Zone F-1, PWD, 12th Floor, MSO Building, I.P. Estate, New Delhi for kind information please.
- (2) The Executive Engineer, FPD, F-131 for information & necessary action please.


Project Manager 22/9