अधीक्षण अभियंता (दक्षिण-पूर्व)एम,

लोक निर्माण विभाग, (रा.रा.क्षेत्र दिल्ली सरकार) सुखदेव विहार, मधुरा रोड, नई दिल्ली-110025 दूरभाष / फैक्स संख्या : 26322484/26837368 ई-मेल आई डी : sepwddelhim42@gmail.com



SUPERINTENDING ENGINEER(SOUTH EAST)M

PWD, (Govt of N.C.T. of Delhi)
Sukhdev Vihar, Mathura Road, New Delhi-110025.
Telephone/Fax No: 26322484/26837368

E-mail ID: sepwddelhim42@gmail.com

F. No. 23(18)/SE/South East (M)/PWD/2017-18/

dt. 13/9/12

INSPECTION NOTE

29/2

Inspection done by Superintending Engineer (South East) M, dated.13.07.2017 time 12.30 to 1.30 PM.

- Inspection of improvement of drainage system in Sujan Singh Mahindar Road,
 New Friends Colony Road, Sarita Vihar Road and Batla House Road are carried out along with Assistant Engineer Shri Sudarshan Kumar.
- Accordingly during the site visit the deficiencies and slow progress of the
 work is asked that by doing personally efforts the speed of the work may be
 increased form the agency. Similarly disposal of unwanted malba/earth are
 also to be disposed of at the earliest so that due to rainy season it may not go
 to the drains. The safety precautions must be taken by the agency. Accordingly
 he should be instructed through Site Order Book also.
- The ROW is to be dealt with the construction of drains in such a way that
 neither drainage nor footpath as well as greenery should be disturbed. The bell
 mouth/chambers are to be taken care so that while completing the work the
 drainage as well as traffic flow should not affected finally on any road which
 has been explained practically at site.

Superintending Engineer (South-East (M), Circle PWD
New Delhi

Copy to:-

- 1. The Chief Engineer, (South)-M, 7th Floor MSO Building New Delhi
- 2. The EE, SER-I, Ishwar Nagar, New Delhi.
- 3. AE, Sh.Sudarshan Kumar SER-I.

Superintending Engineer