

<p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैरो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p>	<p style="text-align: center;"></p> <p style="text-align: center;">E-mail ID : sepwddelhicnd@gmail.com</p>	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
---	---	--

No. 23(15)/SE/C&ND/PWD/2017-18/

4918

Date: 01-11-2017

INSPECTION NOTE

Sub: Inspection undertaken by E-in-C on 29.10.2017 of I.P. Flyover and surrounding area.

E-in-C, PWD carried out inspection of I.P. Flyover and surrounding area. The inspection was attended by the following officers:-

- i. Sh. U.C. Mishra, CE (East) M.
- ii. Sh. V.K. Garg, AE (C&ND) Road.
- iii. Sh. D.N.Gupta, AE(E), DHC&ND/Central (M-451).
- iv. Sh. Shyam Singh, ADH(East).

During the inspection, following directions were given:-

1. Beautification of area below I.P. Flyover is to be completed by 10/11/2017 before LG visit on 11/11/2017.
2. M.S. profile sheet is to be fixed in front of pump house and J.E. incharge ITO office to segregate the area between pump house and developed green area.
3. SFRC / Red sand stone railing is to be provided around areas where horticulture work have been carried like I.P. Flyover, Gulab Vatika, different island etc.
4. Water pipe line should be laid for horticulture purpose below I.P. Flyover.
5. Horticulture work should be improved on all road like Sachivalaya Road, Kishan Ghat Road, Ring Road between Bhairon Marg T-Junction to Shantivan, JLN Marg, BZM, Mathura Road, I.P. Marg, Vikas Marg and Bhairon Road.
6. All minor repair of footpath, toe wall, islands, railing, kerb stone be carried out before Hon'ble LG visit.
7. Painting of kerb stones, railing, crash barrier should be completed before 10/11/2017.
8. At railway xing near PWD office on Ring Road, central verge with existing pattern should be made after removing of steel structure of railing.
9. Repair of road in front of Supreme Court building on Mathura Road should be carried out with DBC.
10. Road safety furniture item like glow studs, solar studs, safety bollards (similar to NDMC pattern), median marker etc. should be provide.
11. Sitting benches of different shape as fixed in Raj Ghat area should be provided under I.P. Flyover, Gulab Vatika etc.
12. Space near Raj Ghat intersection along Ring Road should be developed as horticulture nursery.

13. One toilet block under I.P. Flyover should be developed similar to NDMC pattern.
14. Proper maintenance along with watch and ward should be provided under I.P. Flyover so that area should be maintained on permanent basis.

(मुकेश कुमार)
अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The E-in-C, PWD, 12th floor, MSO Bldg., New Delhi-110002.
2. The Pr. CE (M), PWD, 9th floor, MSO Bldg., New Delhi-110002.
3. The CE (East), PWD, 3rd floor, MSO Bldg., New Delhi-110002.
4. The EE (C&ND) Road (M-413), PWD, Bhairon Road T-Junction, Ring Road, New Delhi-110002.
5. The EE, (DHC/ND) Elect. Divn. (M-451), PWD, Ground Floor, MSO Bldg., Delhi-110054.
6. The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091.
7. Guard file.

ok अधीक्षण अभियन्ता